

	A	B	C	D	E	F	G
1	RAI PREXIM (INDIA) PVT. LTD.						
2	SALES REFERENCE LIST						
3	S.No.	Name of client	Place	Zone	Date of Despatch	Capacity of D.G. Set, Compressor/High Pressure, Ammonia Pumps	Job undertaken
4	1	JCT Electronics Ltd.	Mohali	North	24.03.94	1450 KVA SKODA	Straightening, Grinding of crankshaft, remetalling of bearings & line boring.
5	2	Pashupati Spg. & Wvg. Mills Ltd.	Rewari	North	18.04.94	860 KVA SKODA	Straightening, Grinding of crankshaft, remetalling of bearings & line boring.
6	3	Orissa Synthetics Ltd.	Orissa	East	26.04.94	2270 KVA SKODA	Straightening, Grinding of crankshaft
7	4	Rajasthan Petro Synthetics Ltd.	New Delhi	North	09.06.94	860 KVA SKODA	Straightening, Grinding of crankshaft, remetalling of bearings & line boring.
8	5	Industrial Cables (India) Ltd.	Rajpura, Pb.	North	02.07.94	730 KVA SKODA	Grinding, Remetalling & Line boring of bearings
9	6	M/s Maharaja Shri Umaid Mills Ltd.	Pai	North	14.07.94	860 KVA SKODA	Grinding & Polishing of crankshaft, remetalling of bearings.
10	7	Ballarpur Industries Ltd.	Pondichery, TN	South	26.08.94	2140 KVA SKODA	Straightening, Grinding of crankshaft, supply of bearings & line boring.
11	8	Janakpur Cigarette Factory	Nepal	Overseas	09.09.94	860 KVA SKODA	Straightening, Grinding of crankshaft, remetalling of bearings & line boring.
12	9	Super Spinning Mills Ltd.	Anantapur, Distt. U.P.	South	26.10.94	860 KVA SKODA	Rebuilding of C.R. Pin, grinding, straightening of crankshaft & remetealling of bearings & line boring.
13	10	Recon Synthetics Ltd. Synthetics Ltd.	Allahabad	North	02.11.94	2270 KVA SKODA	Straightening, rebuilding & Grinding of crankshaft.
14	11	Pashupati Spg. & Wvg. Mills Ltd.	Dharuhera	North	05.11.94	608 KVA SKODA	Grinding & Polishing of crankshaft, remetalling of bearings & line boring.
15	12	Recon Synthetics Ltd. Synthetics Ltd.	Allahabad	North	14.01.95	2270 KVA SKODA	Removal of bend, grinding & Polishing of crank shaft
16	13	JCT Electronics Ltd.	Mohali, Pb.	North	17.02.95	1450 KVA SKODA	Straightening, Grinding, Line broing, Remetalling of bearings.
17	14	Verdalakshmi Mills Ltd.	Madurai	South	11.03.95	550 KVA SKODA	Grinding and Polishing of crank shaft.
18	15	Kelvinator of India Ltd.	Faridabad	North	21.03.95	1100 KVA SKL	Straightening & Grinding of crankshaft, remetalling of bearings.
19	16	Soma Textiles and Industries Ltd.	Ahmedabad	West	23.03.95	1450 KVA SKODA	Rebuilding of C.R. Pin, grinding, straightening of crankshaft & remetealling of bearings & line boring.
20	17	Bhilwara Spinners Ltd.	Rajasthan	North	27.03.95	860 KVA SKODA	Grinding of C.R. Pin and Main Journals, Line boring, Remetalling, Straightening.
21	18	Reliance Jute Mills	Calcutta	East	17.04.95	860 KVA SKODA	Grinding of crankshaft.
22	19	Good Year India Ltd.	Faridabad	North	03.05.95	2840 KVA Deutz	Straightening & Grinding of crankshaft.
23	20	Auro Spinning Mills	Solan, HP	North	01.06.95	1600 KVA SKODA	Straightening & Grinding of crankshaft.
24	21	Indian Oil Corporation Ltd.	Digboi, Assam	East	13.06.95	1600 KVA SKODA	Straightening, Grinding, Polishing & Supply of Brgs.
25	22	Vardhman Polylex Ltd.	Bathinda, Pb	North	30.06.95	860 KVA SKODA	Straightening & Grinding of crankshaft, remetalling of bearings & line boring.
26	23	Mahavir Aluminium Ltd.	Bhiwadi	North	05.07.95	1100 KVA SKL	Grinding of Crankshaft, remetalling of bearings & line boring.
27	24	Orissa Synthetics Ltd.	Orissa	East	18.07.95	2270 KVA SKODA	Straightening, Grinding of crankshaft, Repair of CR Housings
28	25	Rajasthan Spinning & Weaving Mills	Gulabpura, Rajasthan	North	26.07.95	860 KVA SKODA	Grinding of Crankshaft, remetalling of bearings & line boring.
29	26	Sidheshwari Paper	Kasipur	North	29.07.95	C.I. Roll	Grinding of C.I. Roll
30	27	Pfizer India Ltd.	Chandigarh	North	01.08.95	860 KVA SKODA	Straightening & Grinding of crankshaft, remetalling of bearings & line boring.
31	28	Amrit Paper	Saila Khurd, Pb.	North	19.08.95	Kluster Roll	Grinding of Kluster Roll
32	29	Hyderabad Industries Ltd.	Faridabad	North	02.09.95	860 KVA SKODA	Grinding of Crankshaft, remetalling of bearings & line boring.
33	30	Kolhapur Zilha Shetkari Soot Girani Ltd.	Kolhapur, Mhrs	West	06.09.95	825 KVA SKODA	Straightening, Grinding of Crankshaft, Manufacturing of bearings.
34	31	Kelvinator of India Ltd.	Faridabad	North	16.09.95	1100 KVA SKL	Straightening, Grinding of Crankshaft & remetalling of bearings & Line boring.
35	32	Modi Vanaspati Mfg. Co.	Modinagar	North	02.10.95	860 KVA SKODA	Straightening, Grinding of Crankshaft & remetalling of bearings & Line boring.
36	33	Bindias Duplex P.Ltd.	Muzzafarnagar, U.P.	North	04.10.95	C.I. Rolls	Grinding of Chilled rolls
37	34	Shree Balaji Forgings Pvt. Ltd.	Bhiwadi	North	05.10.95	460 KVA SKL	Grinding of crankshaft
38	35	Shri Vishnu Cement Ltd.	Hyderabad	South	10.10.95	2270 KVA SKODA	Straightening & Grinding of crankshaft, Repair of CR Housings
39	36	Andra Sugars Ltd.	West Godawari, A.P.	South	13.10.95	2270 KVA SKODA	Grinding of crankshaft
40	37	Varinder Agro Chemicals Ltd.	Ludhiana, Pb.	North	18.10.95	Calander Rolls	Grinding of Calander Rolls.
41	38	Shri Vishnu Cement Ltd.	Hyderabad	South	18.10.95	2270 KVA SKODA	Straightening, Grinding of Crankshaft, Repair of MJ/CR housing.

	A	B	C	D	E	F	G
42	39	Rajasthan Petro Synthetics Ltd.	New Delhi	North	20.10.95	860 KVA SKODA	Straightening, Grinding of crankshaft, Remetalling of bearings, line boring.
43	40	Escorts Ltd.	Faridabad	North	30.10.95	860 KVA SKODA	Straightening, Grinding of crankshaft, Remetalling of bearings, line boring.
44	41	Triveni Sheet Glass Works Ltd.	Allahabad	North	06.11.95	Panel of 2270 KVA Skoda	Home Consumption panel repair.
45	42	Pashupati Spg. & Wvg. Mills Ltd.	Dharuhera, Haryana	North	13.11.95	860 KVA SKODA	Grinding & rebuilding of crankshaft.
46	43	Nahar Fabrics Ltd.	Patiala (Pb.)	North	13.11.95	780 KVA WARTSILA	Straightening and grinding of crankshaft.
47	44	Usha India Ltd.	Sindhudurg Mhrs.	West	05.12.95	2140 KVA SKODA	Straightening and grinding of crankshaft, Supply of bearings.
48	45	Modinagar Paper Mills Ltd.	Modinagar	North	23.12.95	C.I. Roll	Grinding of C.I. Roll
49	46	Jayashree Insulators	Calcutta	East	27.12.95	608 KVA SKODA	Straightening & Grinding of Crankshaft, Remetalling of bearings.
50	47	Sagar Cement Ltd.	Nalgonda	South	13.12.95	1450 KVA SKODA	Grinding & straightening of Crankshaft, remetalling & Line boring.
51	48	Aggarwal Steel Rolling Mills	Mandi, Gobingarh	North	22.01.96	1800 KVA AKASAKA	Grinding of Crankshaft & Remetalling of bearings & Line boring.
52	49	Orphic Dyeing & Printing Pvt. Ltd.	Faridabad	North	11.02.96	590 KVA MAN	Grinding of crankshaft, remetalling of bearings & Line boring.
53	50	Vam Organic & Chemicals Ltd.	Gajraula	North	11.02.96	2270 KVA SKODA	Straightening & grinding of crankshaft & repair of CR bearings housings.
54	51	India Termit Corpn. Ltd.	Kanpur	North	16.02.96	High pressure pumps	Grinding of crankshaft of Pump
55	52	SAF Yeast Co. Ltd.	Hardoi, U.P.	North	08.03.96	840 KVA Mirrlees	Grinding of Crankshaft, remetalling of bearings & line boring.
56	53	Rassi Cement Ltd.	Secunderabad	South	11.03.96	2270 KVA SKODA	Metal stitching of lower & upper block, straightening & grinding of crankshaft, supply of bearings.
57	54	Indian Oil Corpn. Ltd.	Digboi, Assam	East	21.03.96	CKD 1600 KVA	Straightening & Grinding of Crankshaft, Repair of CR /MJ Housing, supply of bearings.
58	55	Recron Synthetics Ltd. Synthetics Ltd.	Naini, U.P.	North	03.04.96	CKD 2270 KVA	Rebuilding of C.R. Pin, grinding, straightening of crankshaft & remetealling of bearings & line boring.
59	56	Shree Synthetics Ltd.	Ujjain	North	04.04.96	860 KVA SKODA	Grinding, straightening & rebuilding of crankshaft, remetalling of bearings and line boring.
60	57	Asarwa Mills	Ahmedabad	West	08.04.96	860 KVA SKODA	Straightening & Grinding of crankshaft, remetalling of bearings & line boring.
61	58	Shri Vishnu Cement Ltd.	Hyderabad, A.P.	South	13.04.96	2270 KVA SKODA	Grinding & rebuilding of crankshaft, repair of CR Housings.
62	59	Aruppukottari Sri Jayavilas Pvt. Ltd.	Arupkottai, T.N.	South	23.04.96	608 KVA SKODA	Straightening & Grinding of crankshaft, rebuilding of C.R. Pin, remetalling of bearings and line boring.
63	60	Jagatjeet Industries Ltd.	Kapurthala (Pb.)	North	17.05.96	608 KVA SKODA	Grinding of Crankshaft, remetalling of bearings & line boring.
64	61	Hindustan Aeronautics Ltd.	Bangalore	South	24.05.96	1150 KVA SKL	Straightening & Grinding of crankshaft, facing of flanges.
65	62	Bhoruka aluminium	Mysore	South	31.05.96	860 KVA SKODA	Straightening & grinding of crankshaft, remetalling bearing & line boring
66	63	Panyam Cement	Hyderabad	South	07.06.96	CKD 2270 KVA	Straightening & grinding of crankshaft, supply of bearings.
67	64	Asarwa Mills	Ahmedabad	West	10.06.96	608 KVA SKODA	Grinding of Crankshaft, remetalling of bearings & line boring.
68	65	Hindustan Gum	Bhiwani	North	13.06.96	CKD 375 KVA	Grinding of crankshaft
69	66	Hyderabad Industries Ltd.	Faridabad	North	18.06.96	860 KVA SKODA	Straightening, grinding of crankshaft, remetalling of bearings & line boring.
70	67	Hindustan Adhesive	New Delhi	North	29.06.96	B & W 650 KVA	Grinding of crankshaft, remetalling of bearings.
71	68	Good Year India Ltd.	Faridabad	North	04.07.96/04.1.96	CKD 860 KVA	Grinding of crankshaft, remetalling of bearings & line boring.
72	69	Pashupati Ltd.	Rewari	North	11.07.96	Controls Panel	Panel Repair
73	70	ITC BPL	Khammam (A.P.)	South	15.07.96	CKD 2270 KVA	Straightening & Grinding of crankshaft, supply of bearings.
74	71	Shakumbhari Paper Mills	Shakumbari Nagar	Overseas	20.07.96	SKL 840 KVA	Grinding of crankshaft
75	72	Pfizer Limited	Chandigarh	North	22.07.96	CKD 860 KVA	Metal stitching of Line Boring of crankcase
76	73	Cimmco Spinners	Sholapur, Mhrs.	West	03.08.96	CKD 825 KVA	Grinding of Crankshaft, supply of undersize bearings line boring of MJ Housings.
77	74	Recron Synthetics Ltd. Synthetics Ltd.	Naini, Allahabad	North	30.08.96	2270 KVA SKODA	Bend Removal and grinding of rotor shaft
78	75	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	30.08.96	2270 KVA SKODA	Grinding of crankshaft
79	76	Khyber Industries	Srinagar, Kashmir	North	05.09.96	Bergen 550 KVA	Grinding of crankshaft
80	77	Bhawani Cotton Mills & Ind. Ltd.	Abohar (Pb.)	North	15.09.96	CKD 860 KVA	Grinding of crankshaft, Line boring, Remetalling of bearings.
81	78	Prestige Vanaspati	Dewas	North	23.09.96	800 KW Cripely	Grinding of crankshaft, supply of bearings.
82	79	Orissa Synthetics Ltd.	Orissa	East	08.10.96	CKD 2270 KVA	Grinding of crankshaft, supply of bearings.
83	80	Hasting Jute	Calcutta	East	30.09.96	1100 KVA SKL	Straightening & Grinding of crankshaft

	A	B	C	D	E	F	G
84	81	Bhawani Cotton Mills & Ind. Ltd.	Abohar (Pb.)	North	09.10.96	CKD 860 KVA	Metal stitching of crankcase
85	82	Hindustan Adhesive	New Delhi	North	10.10.96	B & W 650 KVA	Grinding of crankshaft, remetalting of bearings, supply of undersize bearings, line boring.
86	83	Field Gun Factory	Kanpur	North	14.10.96	High pressure pumps	Grinding of crankshaft of high pressure pumps
87	84	Vardhman Spinning	Ludhiana, Pb.	North	23.10.96	CKD 1600 KVA	Grinding of crankshaft, supply of bearings.
88	85	Geep Industrial Syndicate	Allahabad	North	28.10.96	860 KVA Cylinder Head	Metal Stitching
89	86	Good Year India Ltd.	Faridabad	North	08.11.96	CKD 860 KVA	Grinding of crankshaft, Metallising of bearings & line boring.
90	87	Binny Limited	Bangalore	South	20.11.96	CKD 860 KVA	Grinding of crankshaft, Line boring, Remetalting of bearings.
91	88	Orissa Synthetics Ltd.	Dhenkanal	East	23.11.96	2270 KVA SKODA	Grinding of crankshaft, metal stitching of lower crankcase, supply of undersize bearings.
92	89	Apollo Tyres	New Delhi	North	23.11.96	CKD 1450 KVA	Grinding of crankshaft, Line boring, Remetalting of bearings.
93	90	Vikrant Tyres	Mysore	South	08.12.96	CKD 1450 KVA	Metal stitching of Upper crankcase, crankshaft grinding, Remetalting of bearing & Line boring.
94	91	Pashupati Ltd.	Rewari	North	09.12.96	CKD 860 KVA	Grinding of crankshaft, Line boring, remetalting of bearings.
95	92	Pashupati Spinning tMills	Rewari	North	09.12.96	500 KVA SKODA	Grinding of crankshaft, Line Boring, remetalting of bearings.
96	93	Vikram Ispat	Raigad	West	17.12.96	CKD 3250 KVA	Grinding of crankshaft, line boring, supply of bearings.
97	94	Maral Overseas	H.P.	North	20.12.96	CKD 1600 KVA	Grinding of crankshaft, bearings, straightening of crankshaft.
98	95	Kirti Agro Ind.	Dewas	North	30.12.96	Cylinder Head	Metal Stitching
99	96	Kesoram Industries	Calcutta	East	11.01.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings.
100	97	JCT Limited	Ganganagar	North	16.01.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings
101	98	Modi Rubber	Meerut	North	24.01.97	CKD 860 KVA	Grinding of crankshaft, Line boring, Remetalting of bearings.
102	99	Andman Timber	A & N Island	Overseas	29.01.97	CKD 405 KVA	Grinding of crankshaft, Line boring, Remetalting of bearings.
103	100	Rajasthan Textile Mills	Bhawani Mandi, Raj	North	31.01.97	860 KVA SKODA	Grinding of crankshaft, Line Boring, Remettling of bearings.
104	101	HEG Limited	Udaipur	North	31.01.97	1450 KVA SKODA	Metal Stitching of Upper/Lower Crankcase, Grinding of crankshaft, remetalting of bearings & Line Boring.
105	102	ITC Badhrachalam	Khammam (A.P.)	South	10.02.97	CKD 2270 KVA	Grinding of crankshaft, Supply of undersize bearing.
106	103	GEW Faridabad	Faridabad	North	27.02.97	CKD 860 KVA	Grinding of crankshaft, Line boring, remetalting of bearings.
107	104	Surya Roshni	B'garh	North	07.04.97	CKD 860 KVA	Grinding of crankshaft, Line boring, Remetalting of bearings.
108	105	Anant Spinning Mills	Bhiwani, Mandi	North	10.04.97	CKD 2140 KVA	Grinding of crankshaft, Supply of undersize bearings
109	106	Ginni Filaments Ltd.	Kosikalan	North	15.04.97	CKD 860 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
110	107	Dabur	Ghaziabad	North	21.04.97	Mirrlees 1200 KVA	Straightening of the crankshaft and also for N.D. Tests of MJ & CR Pins.
111	108	Prestige Vanaspati	Dewas	North	22.04.97	960 KVA Sulzer	Grinding of crankshaft, remetalting of bearings and line boring.
112	109	The Co-operative Textile	Bulandsher	North	24.04.97	1100 KVA Russian	Metal stitching of cylinder head.
113	110	Ganesh Foundry	Muzzafarpur, Bihar	East	25.04.97	Deutz 1340 KVA	Straightening & Grinding of crankshaft.
114	111	Sir Shadilal Ltd.	Muzzafar nagar	North	28.04.97	250 HP Sulzer	Grinding of crankshaft
115	112	Upper Ganges Ltd.	Shivhara, Bijnor	North	30.04.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings.
116	113	Apollo Tyres	Baroda	West	10.05.97	CKD 2270 KVA	Grinding of crankshaft, supply of bearings.
117	114	OBL Rihikesh	Rishikesh	North	22.05.97	CKD 608 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
118	115	Indian Alluminium	Faridabad	North	26.05.97	CKD 860 KVA	Grinding of crankshaft, Line Boring, remetalting of bearings.
119	116	Mafatlat Industries Ltd.	Ahmedabad	West	28.05.97	CKD 825 KVA	Grinding of crankshaft, supply of bearings & metal stitching of lower crankcase.
120	117	H.P. Cotton Mills	Hissar	North	10.06.97	CKD 860 KVA	Grinding of crankshaft, line boring, remetalting of bearings.
121	118	Usha Ispat	Sindhurg (MH)	West	16.06.97	CKD 2270 KVA	Grinding of crankshaft, supply of bearings.
122	119	Indian Rayon Ind. Ltd.	Jodhpur, Raj	North	18.06.97	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
123	120	Shree Bhawani Cotton Mills & Ind. Ltd.	Ganganagar	North	27.06.97	CKD 500 KVA	Grinding of crankshaft, remetalting of bearings & Line boring.
124	121	GEW Bharatpur	Bharatpur	North	09.07.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings & line boring.
125	122	J.P. Rewa Cement	Rewa, M.P.	North	12.07.97	Modi Mirrlees 6 MW	Straightening of crankshaft by pinning process & grinding of crankshaft.

	A	B	C	D	E	F	G
126	123	Tisco Ltd.	Calcutta	East	14.07.97	CKD 1450 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
127	124	Delta Jute	Calcutta	East	14.07.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings & Line boring.
128	125	Bhilwara Spinners Ltd.	Bhilwara (Raj)	North	07.08.97	CKD - 860 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
129	126	Orient Syntex	Alwar	North	07.08.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
130	127	Kalyani Engineering	Ghaziabad	North	14.08.97	Pump shaft	Grinding of pump shaft
131	128	Gokak Vadodara Ltd.	Vadodara	West	20.08.97	500 KVA SKODA	Grinding of Crankshaft, remetalting of bearings & line boring.
132	129	Polyplex Corporation Ltd.	Udhamsingh Nagar, U.P.	North	27.08.97	CKD 1720 KVA	Total inspection and UT Test of crankshaft and other spares
133	130	Bindlas Duplex P.Ltd.	Muzafarnagar, U.P.	North	02.09.97	CKD 1450 KVA	Grinding of crankshaft, remetalting of berings & Line Boring.
134	131	J.K. Jute Mills Ltd.	Kanpur	North	02.09.97	CKD 860 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
135	132	Dewan Rubber Ltd.	Meerut	North	13.09.97	CKD 860 KVA	Metal stitching of cyl. Head.
136	133	Andhra Cements	Visakapatnam	South	16.09.97	Kirloskar Pielstick	Inspection of crankshaft
137	134	SPL Limited	Kassar (Haryana)	North	10.10.97	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
138	135	Ganges Industries	Calcutta	East	14.10.97	CKD 1450 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
139	136	Auto Pins (I) Ltd.	Faridabad	North	21.10.97	460 KVA SKL	Grinding of crankshaft, remetalting of bearings and also for MP, UT and other tests
140	137	Shree Synthetics Ltd.	Ujjain	North	24.10.97	CKD 860 KVA	Grinding of Crankshaft, remetalting of bearings & line boring.
141	138	Kisan Industries Ltd.	Ahmedabad	West	10.11.97	Bergen 830 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
142	139	Garware Polyester Ltd.	Mumbai	West	13.11.97	CKD 1450 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
143	140	Hindustan Wire Ltd.	Faridabad	North	22.11.97	CKD 860 KVA SKODA	Grinding of crankshaft, remettling of bearings and line boring.
144	141	Jain Textile	Gurgaon	North	25.11.97	687.5 KVA MAN	Grinding of crankshaft, remetalting of bearings and line boring.
145	142	Synthetics & Chemicals Ltd.	Bareilly	North	05.12.97	3250 KVA SKODA	Grinding of crankshaft, supply of bearings.
146	143	Auro Spinning Mills	Solan, H.P.	North	11.12.97	1600 KVA SKODA	Connecting Rod Housings
147	144	Almora Magnetise	Almora	North	07.01.98	608 KVA SKODA	Grinding of crankshaft & metallizing of bearing.
148	145	National Fertilizers Ltd.	Guna	North	07.01.98	Pump shaft of Ammonia Feed Pump	Rebuilding and grinding of crank shaft
149	146	Thirumalai Chemicals	Ranipet, T.N.	South	14.01.98	1100 KVA SKL	Grinding of crankshaft
150	147	Pasupati Spinning Mills	Dharuhera, Haryana	North	23.01.98	860 KVA Skoda	Grinding of crankshaft, remetalting of bearings and line boring.
151	148	Rajshree Polyfill	Bharuch	West	07.02.98	2270 KVA SKODA	Straightening of camshaft
152	149	Raj Steel Rolling Mills	Mandi Gobindgarh	North	07.02.98	1200 HP MAN	Grinding of crankshaft, remetalting of bearings
153	150	Dabur India Ltd.	Ghaziabad	North	09.02.98	1200 KVA Mirrlees Blackstone	Grinding of crankshaft
154	151	Hindustan National Glass	B'Garh	North	18.02.98	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
155	152	Fenner India Ltd.	Salem	South	27.02.98	860 KVA SKODA	Grinding of crankshaft, rebuilding of MJ bearings, line boring.
156	153	JCT Limited	Hoshiarpur	North	06.03.98	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
157	154	Jaipur Polyspin	Sikar, Raj	North	19.03.98	1150 KVA SKL	Grinding of crankshaft, remetalting of bearings and line boring.
158	155	Jain Camer	Gurgaon	North	26.03.98	7.5 MW Steam Turbine	Grinding of Turbine Shaft
159	156	Kisan Industries Ltd. (II Shaft)	Ahmedabad	West	11.04.98	830 KVA Bergen	Grinding of crankshaft, rebuilding of CR Pin and supply of bearings.
160	157	Rishab Spinning Mills	Ludhiana, Pb.	North	18.04.98	1100 KVA Russian	Metal stitching of cylinder heads.
161	158	Lauls Ltd.	Faridabad	North	29.04.98	1250 Fuji Make	Grinding of crankshaft, line boring, remetalting of bearings.
162	159	Torrent Gujarat Biotech Ltd.	Vadodara	West	05.05.98	2270 KVA SKODA	Grinding of crankshaft.
163	160	Torrent Gujarat Biotech Ltd.	Vadodara	West	05.05.98	2270 KVA SKODA	Grinding of crankshaft, Line boring and supply of bearings.
164	161	Aarvee Denims	Ahmedabad	West	07.05.98	500 KVA SKODA	Grinding of crankshaft, remetalting of bearings & Line boring.
165	162	Chadha Paper Mills	Moradabad	North	08.05.98	500 KVA Kirloskar	Rebuilding and grinding of crankshaft
166	163	Rico Auto	Gurgaon	North	06.06.98	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of other spares.
167	164	Precision Diesel Engg.	Delhi	North	08.06.98	608 KVA SKODA	Grinding of crankshaft, remetalting of bearings & Line boring.

	A	B	C	D	E	F	G
168	165	Kashiram Textile Ind.	Ahmedabad	West	20.06.98	375 KVA MAN	Grinding of crankshaft
169	166	Mahavir Spinning Mills	Hoshiarpur	North	06.07.98	1600 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of other spares.
170	167	Mico Limited	Bangalore	South	06.07.98	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings & Line boring.
171	168	Kirloskar Oil Engines Ltd.	Nasik (Mhrs.)	West	04.08.98	Pielstick Crank shaft	Grinding of Crankshaft 3 nos.
172	169	Konkan Synthetics	Mahad	West	05.08.98	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of other spares
173	170	Hooghly Mills Co. Ltd.	Calcutta	East	06.08.98	860 KVA Skoda	Grinding of crankshaft, remetalting of bearings & line boring.
174	171	Havells India Limited	Alwar	North	24.08.98	650 KVA B & W	Grinding of crankshaft, remetalting of bearings and repair of other parts
175	172	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	31.08.98	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of other spares.
176	173	Bhilwara Spinners Ltd.	Bhilwara (Raj)	North	10.09.98	CKD 860 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
177	174	Murgappa Morgan Thermal Ceramics Ltd.	Ranipet, T.N.	South	11.09.98	1100 KVA SKL	Inspection of all spare parts.
178	175	Vishwanath Iron & Steel	Mandi, Gobingarh	North	14.09.98	1500 BHP Deutch	Grinding of crankshaft, remetalting of bearings, line boring and repair of housings.
179	176	Radhey Lal Sugar	Bareilly	North	23.09.98	500 KVA Sulzer	Grinding of crankshaft
180	177	J.P. Sugar Ind. Ltd.	Lakhimpur	North	25.09.98	450 KVA Fiat	Grinding of Crankshaft, remetalting of bearings & line boring.
181	178	National Steels	Indore	North	16.10.98	5 MW Ruskie	Rebuilding and grinding of crankshaft.
182	179	Vikram Ispat	Raigad	West	28.10.98	3250 KVA Skoda	Grinding of crankshaft, repair of MJ/CR housings and supply of bearings.
183	180	K.G. Naidu	Coimbatore	South	07.11.98	1200 KVA Mirrlees Blackstone	Complete inspection of crankshaft and crack detection tests
184	181	Rameshwar Prasad Cane Crusher	Bijnor	North	17.11.98	500 KVA SKL	Straightening, Gringing of crankshaft, remetalting of bearings and line boring.
185	182	Rajasthan Rajya Sahakari Sugar Mills	Hanumangarh	North	18.11.98	860 KVA SKODA	Straightening, Grinding of crankshaft, remetalting of bearings and line boring.
186	183	Century Denim	Indore	North	02.12.98	1525 KVA SKODA	Rebuilding/Straightening, Grinding of crankshaft, remetalting of bearings and line boring.
187	184	Ralson India Ltd.	Ludhiana, Pb.	North	09.12.98	2675 KVA Mirrlees	Rebuilding of CR Pin, Grinding of crankshaft, remetalting of bearings and line boring.
188	185	Soma Textiles-II	Pune	West	20.12.98	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of MJ Housings.
189	186	Lakshmi Cements	Sirohi, Raj	North	26.12.98	6 MW Mirrlees	Grinding of crankshaft & repairing of CR Housings.
190	187	SRF Limited	Gwalior	North	07.01.99	2270 KVA SKODA	Grinding of crankshaft.
191	188	Modi Rubber	Modipuram	North	18.01.999	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
192	189	JCT Limited	Hoshiarpur	North	19.01.99	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
193	190	Hafed Spinning Mills	Hansi	North	23.01.99	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
194	191	Indian Rayon Ind. Ltd.	Veraval, Guj	West	02.02.99	2270 KVA SKODA	Repair of CR Housings
195	192	Hindustan Sanitaryware Ind. Ltd.	Bahadurgarh	North	13.02.99	4165 Mirrlees	Repair of CR Housings
196	193	Century Enka	Pune	West	15.02.999	2270 KVA SKODA	Grinding and Straightening of crankshaft, Supply of bearings.
197	194	Quality Foils Limited	Hissar	North	16.02.99	625 KVA Creppley	Grinding of crankshaft
198	195	Lakshmi Cements	Sirohi, Raj	North	18.02.99	6 MW Mirrlees	Grinding of crankshaft and repair of CR housing.
199	196	Vikas Steel & Alloys Ltd.	Sonepat	North	03.03.99	405 KVA SKODA	Grinding of crankshaft, supply of CR/MJ brgs. And repair of other parts.
200	197	Sholingur Textile	Sholingur, T.N.	South	04.03.99	405 KVA SKODA	Grinding of crankshaft, supply of CR/MJ brgs. And repair of other parts.
201	198	Malwa Cotton Mills	Barnala	North	05.03.99	1100 KVA SKL	Grinding of crankshaft & Line Boring of Lower Crankcase
202	199	Soma Textiles-I	Pune	West	15.03.99	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of other parts.
203	200	K.L. Steel	Ghaziabad	North	17.03.99	1200 HP MAN	Grinding of crankshaft, manufacturing of bearings
204	201	Fenner India Ltd.	Dharamपुरi, T.N.	South	20.03.99	825 KVA SKODA	Grinding of crankshaft, supply of bearings.
205	202	Pasupati Spinning & Wvg. Mills	Rewari	North	27.03.99	608 KVA SKODA	Grinding of crankshaft, supply of bearings.
206	203	Triveni Synthetics Yarn Ind. Ltd.	Nepal	Overseas	27.03.99	405 KVA SKODA	Reconditioning of crankshaft, remetalting of bearings and line boring.
207	204	Soma Textile-II	Pune	West	03.04.99	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of MJ Housings.
208	205	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	10.04.99	2270 KVA SKODA	Repair of CR Housings
209	206	Vam Organics & Chemicals Ltd.	Gajraula	North	21.04.98	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.

	A	B	C	D	E	F	G
210	207	Torrent Gujarat Biotech Ltd.	Vadodara	West	27.04.99	2270 KVA SKODA (Key way)	Grinding of crankshaft, supply of bearings and repair of other necessary spares, manufacturing of key
211	208	Vardhman Spinning Mills	Ludhiana, Pb.	North	28.04.99	1600 KVA SKODA	Grinding of rotor shaft
212	209	Hindustan National Glass	B'Garh	North	03.05.99	4125 KVA SULZER	Grinding of crankshaft
213	210	JCT Limited	Phagwara	North	12.05.99	1100 KVA SKL	Overhauling of D.G. Set, Grinding/Metallizing of bearings and line boring.
214	211	Hyderabad Industries Ltd.	Faridabad	North	13.05.99	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
215	212	SRF Limited	Gwalior	North	18.05.99	2270 KVA SKODA	Repair of CR Housings
216	213	Rathi Industries	Ghaziabad	North	29.05.99	650 KVA SULZER	Grinding of crankshaft
217	214	Paswara Paper Mills	Meerut	North	02.06.99	840 KVA SKL	Grinding of crankshaft
218	215	Surya Processors	Ghaziabad	North	05.06.99	780 KVA WARTSILA	Grinding of crankshaft
219	216	Arham Spinning Mills	Bhiwani	North	16.07.99	1000 KVA Russian	Grinding of cam shaft.
220	217	K.L. Concast	Ghaziabad	North	21.07.99	1000 KVA Mirrlees	Grinding of crankshaft, remetalting of bearings and line boring.
221	218	Bhilwara Spinners Ltd.	Bhiwara	North	28.07.99	860 KVA Skoda	Grinding of crankshaft, remetalting of bearings and line boring.
222	219	Gorakhali Rubber Udyog	Calcutta	East	28.07.99	405 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
223	220	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	29.07.99	2270 KVA SKODA	Straightening & Grinding of crankshaft, supply of bearings.
224	221	Tisco Ltd.	Hazaribagh	East	24.08.99	2.5 MW Bergen	Straightening, Rebuilding & Grinding of crankshaft, supply of bearings.
225	222	Motors India Co. Ltd.	Bangalore	South	27.08.99	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings, line boring and repair of other parts.
226	223	Tata Chemical	Badaun	North	27.08.99	Pump Sleeve	Development and Supply of sleeves
227	224	Magnum Power Generation Ltd.	Gurgaon	North	27.08.99	6 mw Deutz	Inspection, repair of liners and manufacturing of gear shaft.
228	225	Swastik Steels Pvt. Ltd.	Mumbai	West	28.08.99	Daihatsu DS-26	Grinding of crankshaft, repair of main journals/CR Housings
229	226	Owens Brockway Pvt. Ltd.	Rishikesh	North	31.08.99	275 KVA RUSTON	Grinding of crankshaft
230	227	SRF Limited	Gwalior	North	02.09.99	2270 KVA SKODA	Repair of CR Housings
231	228	WBSEB-I	Calcutta	East	02.09.99	730 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
232	229	Ghanshyam Sugar Ind.	Lakhimpur	North	06.09.99	400 KVA Fiat	Grinding of crankshaft, remetalting of bearings and line boring.
233	230	Shri Shiv Shankar Sugar Ind.	Lakhimpur	North	06.09.99	400 KVA Fiat	Grinding of crankshaft, remetalting of bearings and line boring.
234	231	Konkan Synthetics	Pune	West	16.09.99	2270 KVA SKODA	Grinding of crankshaft, repair of CR Housings and supply of bearings.
235	232	Triveni Synthetics Ind.	Nepal	Overseas	20.09.99	405 KVA SKODA	Grinding of crankshaft, remetalting of bearings & Line boring.
236	233	K.L. Concast	Ghaziabad	North	24.09.99	460 KVA BERGEN	Grinding of crankshaft, remetalting of bearings and line boring.
237	234	Orissa Synthetics Ltd.	Orissa	East	01.10.99	2270 KVA SKODA	Key way Manufacturing, Grinding of crankshaft and supply of bearings
238	235	U.P. Twiga Fibre Glass	Sikandrabad	North	11.10.99	1722 KVA Ruston	Grinding of crankshaft and supply of bearings
239	236	H.P. Cotton Mills	Hissar	North	16.10.99	1450 KVA SKODA	Grinding of crankshaft, metallizing of bearings and line boring.
240	237	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	30.10.99	2270 KVA SKODA	Grinding of crankshaft
241	238	Venmeer Mills	Mysore	South	01.11.99	NT-743 Kirloskar	Rebuilding and grinding of crankshaft
242	239	Satna Cement Works	Satna	North	10.11.99	Raw Mill & Cement Mill	Development and Manufacturing of bearings
243	240	Maral Overseas	Khargaon	North	10.11.99	1525 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
244	241	Magnum Power Generation Ltd.	Gurgaon	North	15.11.99	6 MW Deutz	Honing of 4 nos. Liners
245	242	Surya Roshni	Bahadurgarh	North	26.11.99	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
246	243	Hindustan Everest Tools	Sonepat	North	08.12.99	1100 KVA SKL	Grinding of Crankshaft
247	244	Rico Auto	Gurgaon	North	09.12.00	2270 KVA SKODA	Repair of CR Housing
248	245	TIL Ltd.	Ghaziabad	North	21.12.99	625 KVA TIL	Inspection of crankshaft
249	246	Universal Glass	Sahibabad	North	22.12.99	500 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
250	247	Pioneer Spinners	T.N.	South	27.12.99	500 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
251	248	SRF Limited	Gwalior	North	27.12.99	2270 KVA SKODA	Repair of CR Housings.

	A	B	C	D	E	F	G
252	249	Satna Cement Works	Satna	North	08.01.00	2650 KW Siemens Motor	Development and Manufacturing of bearings.
253	250	Orient Ceramics	Sikandrabad	North	08.01.00	780 KVA SULZER	Grinding of crankshaft & other related spares, overhauling of D.G. Set
254	251	JCT Limited	Ganganagar	North	12.01.00	860 KVA SKODA	Rebuilding of CR Pin, Grinding of crankshaft, remetalting of bearings and line boring.
255	252	Hindon River Mills Ltd.	Ghaziabad	North	12.01.00	1450 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
256	253	Shree Cement	Beawar	North	20.01.00	4 MW Daihatsu	Grinding of crankshaft, honing of liners, repair of MJ/CR housings and supply of bearings.
257	254	Nellimarla Jute Mills	Vizigram	Overseas	21.01.00	860 KVA SKODA	Grinding of crankshaft, and line boring
258	255	Cordite Factory	Aruvankadu	Overseas	21.02.00	Compressor Shaft	Repair of Ammonia Compressor Piston Shaft.
259	256	Century Enka Ltd.	Pune	West	03.03.00	2270 KVA SKODA	Reconditioning of crankshaft, lower crankcase, repair of MJ/CR housings, supply of MJ/CR bearings.
260	257	Century Enka Ltd.	Pune	West	03.03.00	CKD 2270 KVA	Repair of lower crankcase
261	258	Arihant Spinning Mills	Malerkotla	North	06.03.00	1100 KVA SKL	Grinding of crankshaft, supply of undersize bearings.
262	259	Indian Rayon Ind. Ltd.	Veraval, Guj	West	06.03.00	2270 KVA SKODA	Repair of crankshaft, supply of bearings.
263	260	Century Denim	Khargone, M.P.	North	22.03.00	CKD 1525 KVA	Grinding of crankshaft, remetalting of bearings and line boring.
264	261	Recron Synthetics Ltd. Synthetics Ltd.	Allahabad	North	28.03.00	2270 KVA SKODA	Grinding of crankshaft and supply of bearings
265	262	Vikram Ispat	Raigad	West	31.03.00	3250 KVA Skoda	Grinding of crankshaft, Fabrication of counter weights, repair of MJ/CR Housings, balancing of
266	263	Owens Brockway Pvt. Ltd.	Rishikesh	North	13.04.00	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring
267	264	SPL Limited	Kassar (Haryana)	North	14.04.00	860 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
268	265	Hindustan National Glass	Bahadurgarh	North	20.04.00	4125 KVA SULZER	Overhauling of D.G. Set
269	266	Rana Papers Limited	Muzafarnagar	North	04.05.00	1200 HP Allen	Grinding of crankshaft, Repair of CR Housings.
270	267	Bengal Tea Company	Lakhimpur, Assam	East	05.05.00	405 KVA SKODA	Grinding of crankshaft, metallizing of bearings and line boring.
271	268	National Fertilizers Ltd.	Nangal	North	15.05.00	Ammonia Pump Shaft	Grinding of crankshaft
272	269	Birla Cement Works	Satna	North	19.05.00	Toshiba/ Siemens Motor	Development and Manufacturing of bearings
273	270	Ambuja Cements	Raipur	North	26.05.00	6 MW Wartsila	Honing of Liners
274	271	Hindustan National Glass	Bahadurgarh	North	29.05.00	1200 KVA Mirrlees Blackstone	Inspection of C.R. Housings
275	272	Orphic Dyeing & Printing Pvt. Ltd.	Faridabad	North	30.05.00	1040 KVA Sulzer	Grinding of crankshaft
276	273	Alps India Ltd.	Ghaziabad	North	03.06.00	1000 KVA Wartsila	Piston Crown Inspection
277	274	Pashupati Spinning & Weaving Mills	Dharuhera	North	06.06.00	2.25 MW Wartsla	Piston Crown Inspection
278	275	Tirupati Cylinders	Muzafarnagar	North	06.06.00	500 KVA SKL	Grinding of crankshaft
279	276	Agarpara Jute Mills	Calcutta	East	10.06.00	608 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
280	277	Tata Chemicals	Badann	North	10.06.00	Top shaft of drain recovery	Development and Supply of top shaft
281	278	Northern Railway Shakurbasti	Shakurbasti	North	14.06.00	Locomotive Engine	Line Boring of Crankcase
282	279	Thirumagal Mills	Gudiyattam, T.N.	South	15.06.00	860 KVA SKODA	Grinding of crankshaft, remetalting of corresponding bearings and metal stitching of LCC
283	280	National Fertilizers Ltd.	Nangal	North	24.06.00	G-1345 Shaft	Grinding of crankshaft
284	281	JK Cement	Nimbahera	North	27.06.00	4 MW Fuji	Grinding of crankshaft
285	282	Shamken Multifab Limited	Mathura	North	06.07.00	860 KVA SKODA	Rebuilding/grindingof crankshaft, metallising of bearings and line boring.
286	283	K.L. Concast	Ghaziabad	North	08.07.00	1548 KVA Mirrlees Blackstone D.G. Set	Grinding of crankshaft, remetalting of bearings and line boring.
287	284	M.V. Cotspin Ltd.	Nimrana	North	12.07.00	500 KVA Caterpillar	Metal stitching of cylinder heads.
288	285	Rana Papers Limited	Muzafarnagar	North	14.07.00	2 Nos. crankshafts of 1200 HP	Grindingof crankshaft and repair of CR Housings
289	286	W.B.S.E.B.-II	Calcutta	East	20.07.00	730 KVA SKODA	Grinding of crankshaft, remetalting of bearings and line boring.
290	287	Nova Petrochemical	Ahmedabad	West	22.07.00	Russian	Metal stitching of cylinder heads
291	288	Vikram Ispat	Raigad	West	29.07.00	3250 KVA Skoda	Grinding of crankshaft, supply of bearings and repair of main journal housing.
292	289	Ordnance Factory	Ambajhari	West	11.08.00	Pump shaft	Grinding of shaft
293	290	Northern Railway Shakurbasti	Shakurbasti	North	17.08.00	Engine Block	Line boring

	A	B	C	D	E	F	G
294	291	Janta Khandsari Mills	Muzafarnagar	North	19.08.00	BONN	Grinding of crankshaft, remetalting of corresponding bearings.
295	292	Ginni International Ltd.	Alwar, Rajasthan	North	01.09.00	3 MW Wartsila	Reconditioning of cylinder heads + CR Housings Caps
296	293	Torrent Gujarat Biotech Ltd.	Baroda	West	05.09.00	2270 KVA SKODA	Straightening & Grinding of crankshaft, key way Manufacturing, supply of bearings.
297	294	Verma Brothers Sugar Ind.	Sitapur, UP	North	07.09.00	160 KVA Russian	Repair of 2 nos. crankshafts
298	295	Aarvee Denims	Ahmedabad	West	08.09.00	500 KVA Skoda	Remetalting of CR bearings
299	296	ISGEC	Yamunagar	North	12.09.00	1150 KVA SKL	Inspection of C.S. + L.C.C.
300	297	Ambuja Cements	Raipur	East	18.09.00	6 MW Wartsila	Honing of liner
301	298	Sriram Sugar Ind.	Lakhimpur, Kheri	North	19.09.00	MAC	Grinding + Line boring of crankshaft
302	299	Nova Petrochemical	Ahmedabad	West	21.09.00	Russian	Metal Stitching of cylinder heads
303	300	Shiv Bhagwan Industries	Nepal	Overseas	28.09.00	CKD 405 KVA	Crankshaft grinding, remetalting of bearings and line boring.
304	301	H.P. Cotton Mills	Hisar	North	04.10.00	SKODA 860 KVA	Reconditioning, remetalting and keyway cutting.
305	302	Hindustan Vidyut Ltd.	Faridabad	North	04.10.00	860 KVA SKODA	Grinding, Line Boring of crankshaft and remetalting of bearings.
306	303	Vikram Ispat Ltd.	Raigad	West	11.10.00	3250 KVA Skoda	Crankshaft grinding, bearing supply + LCC Repair + C. Rod repair.
307	304	Technomoy System	Sweden	Overseas	12.10.00	Pielstick	Grinding of crankshaft
308	305	Indian Rayon Ind. Ltd.	Veraval, Guj	West	13.10.00	2270 KVA SKODA	Grinding of crankshaft, supply of bearings and repair of lower crankcase, connecting rods.
309	306	Hindustan National Glass	Bahadurgarh	North	13.10.00	4125 KVA SULZER	Repair of engine block, C.R. Housings, pistons and overhauling
310	307	Ellin Electronics	Ghaziabad	North	17.10.00	608 KVA SKODA	Straightening, rebuilding, grinding and remetalting of corresponding bearings
311	308	SPL Limited	Bahadurgarh	North	20.10.00	2310 KW Sulzer	Grinding of crankshaft
312	309	Birla Corporation Ltd.	Satna(M.P.)	North	20.11.00	Alternator Rotor Shaft, Turbine	Grinding and polishing of shaft, remetalting of turbine bearings
313	310	Nova Petrochemical	Ahmedabad	West	09.11.00	Russian Cylinder head	Metal stitching of cylinder heads
314	311	Lafarge India	Raipur	North	Site	ABB Make Turbocharger	Metal stitching at site
315	312	Owens Brockway Pvt. Ltd.	Rishikesh	North	22.11.00	275 KVA RUSTON	Grinding and polishing of crankshaft.
316	313	Orient Fans	Faridabad	North	23.11.00	500 KVA SKODA	Crankshaft and camshaft beyond repair
317	314	Torrent Gujarat Biotech Ltd.	Baroda	West	29.11.00	2270 KVA SKODA	Repair of CR Housings
318	315	Pragati Paper Mills	Sahibabad	North	29.11.00	100 KVA Kir. Cummins	Inspection of crankshaft.
319	316	Magnum Power Generation Ltd.	Gurgaon	North	30.11.00	6.3 MW Deutz	Repair of CR Housing
320	317	Rico Auto	Gurgaon	North	09.12.00	CKD 2270 KVA	Rectification of 3 nos. C.R. Housings
321	318	Century Yarn	Kargaon	North	10.12.00	1525 KVA SKODA	Grinding of crankshaft, metallising of bearings.
322	319	Aarvee Denims	Ahmedabad	West	12.12.00	500 KVA SKODA	Grinding of crankshaft, metallising of bearings.
323	320	Modipon Fibres Ltd.	Modinagar	North	16.12.00	5 MW Wartsila	Connecting Rods
324	321	National Thermal Power Corporation	Anta, Kota	North	23.12.00	2875 KVA MAK D.G. Set	Repair of Crankshaft & Connecting Rods
325	322	Shamken Spinners Limited	Kosi Kalan	North	26.12.00	25070 KVA Caterpillar	Repair of crankshaft, metal stitching of Engine Block, Line Boring and repair of CR Housings.
326	323	Olympic Pertochemicals	Meerut	North	26.12.00	B & W	Grinding of Crankshaft
327	324	Vikram Ispat	Raigad	West	29.12.00	3250 KVA CKD	Development and Remetalting of non-drive end bearing
328	325	National Fertilizers Ltd.	Nangal	North	02.01.01	Carbamate Pump	Grinding of Crankshaft
329	326	Northern Railway	Shakurbasti	North	03.01.01 30.01.01	Locomotive Engine (2 Nos.)	Line Boring of Lower Crankcase.
330	327	Orient Ceramics	Sikandrabad	North	10.01.01	Sulzer 780 KVA	Repair of cylinder head
331	328	Ginni Filaments Ltd.	Kosikalan	North	22.11.00 17.01.01	2.2 MW Wartsila	Inspection of crankshaft and boring of cylinder head
332	329	Ajanta Papers	Bharuch	West	20.01.01	Kirloskar Pielstick	Crankshaft and Lower Crankcase
333	330	Rassi Cement Ltd.	Nalangonda	South	25.01.01	2270 KVA SKODA	Grinding of crankshaft, Repair of LCC and supply of undersize bearings (Rectification)
334	331	M.V. Cotspin Ltd.	New Delhi	North	06.02.01	350 KVA Caterpillar	Metal stitching of cylinder heads.
335	332	Wartsila India Ltd.	New Delhi	North	08.02.01	Wartsila 4 MW	Machining of cylinder heads and reaming of oil holes in connecting rods.

	A	B	C	D	E	F	G
336	333	J.C. T. Limited	Hoshiarpur	North	08.02.01	4 MW Fuji	Repair of connecting rods
337	334	S.R. F. Limited	Malanpur (M.P.)	North	09.02.01	2270 KVA SKODA	Repair of crankshaft, Lower Crankcase and CR Housings.
338	335	National Fertilizers Ltd.	Naya Nangal	North	12.02.01	Boiler	Development, Manufacturing & supply of weld seals for waste heal boiler.
339	336	Rolls Royce	Gurgaon	North	15.02.01	5 MW Allen	Piston pin repair and rectification of cylinder heads
340	337	Sri Velyudhaswamy Spinning Mills Ltd.	Dindugal (T.N.)	South	24.02.01	320 KVA SKODA	Repair of L.C. C., Crankshaft and connecting rods.
341	338	Rico Auto	Gurgaon	North	28.02.01	2270 KVA SKODA	Repair of crankshaft, LCC, CR Housings and supply of bearings.
342	339	Nova Petrochemicals	Ahmedabad	West	07.03.01	1000 KVA Russian	Metal stitching of cylinder heads
343	340	Rolls Royce	Gurgaon	North	12.03.01	5 MW Allen Engine	Repair of Pistons/ Cylinder heads
344	341	Indian Rayon Ind. Ltd.	Veraval, Guj	West	20.03.01	2270 KVA Skoda	Repair of CR Housings
345	342	Flex Industries Ltd.	Noida	North	20.03.01	Kirloskar Pielstick	Inspection of CR Housings
346	343	IFFCO Ltd.	Phulpur	North	26.03.01	Used Crankshaft	Rebuilding and grinding of crankshaft
347	344	Orissa Synthetics Ltd.	Baulpur, Orissa	East	27.03.01	Alternator rotor shaft	Grinding and polishing of alternator rotor shaft
348	345	Shyam Powertech Ltd.	Bhav Nagar	West	28.03.01	Sulzer5 AL-25/30	Grinding and polishing of crankshaft for export.
349	346	Nova Petrochemicals Ltd.	Ahmedabad	West	29.03.01	Russian Engine 1000 KVA	Metal Stitching of Cylinder Heads
350	347	Grasim Industries Ltd. (Indian Rayon & Industries)	Jodhpur, Raj	North	29.03.01	SKODA 1450 KVA	Repair of crankshaft and other related services
351	348	National Hydroelectric Power Corpn.	Jyotipuram	North	30.03.01	825 KVA SKODA	Repair of Lower crankcase and crankshaft
352	349	Vikram Ispat	Raigad (MHRS)	West	31.03.01	3250 KVA SKODA	Repair of damaged engine blocks
353	350	TIL Ltd.	Ghaziabad	North	10.04.01	Hydraulic Cylinder	Grinding, Chromeplating, polishing of piston tube of the hydraulic cylinder
354	351	Nepal Boards Ltd.	Nepal	Overseas	19.04.01	405 KVA SKODA	Reconditioning of crankshaft
355	352	Recron Synthetics Ltd.	Allahabad	North	24.04.01	2270 KVA SKODA	Repair of engine block
356	353	Nova Petrochemicals Ltd.	Ahmedabad	West	01.05.01	Cylinder heads	Metal stitching of cyloinder heads of Russian Engine
357	354	Industrial Processors & Metallizers P. Ltd.	Delhi	North	04.05.01	Shaft	Repair of shaft
358	355	The Northern Railway	Delhi	North	09.05.01	Crankshaft of WDS4	Reclamation of crankshaft of WDS4
359	356	Ramalinga Mills Ltd.	Tamil Nadu	South	09.05.01	SKODA 608 KVA	Reconditioning of crankshaft
360	357	Madhusudan Ceramics Ltd.	Mehsana	North	10.05.01	500 KVA SKODA	Repair of crankshaft
361	358	Madhusudan Ceramics Ltd.	Mehsana	North	10.05.01	Bearings 500 KVA SKODA	Metallising of bearing
362	359	Hindustan Aeronautics Ltd.	Bangalore	South	15.05.01	1150 KVA SKL	Regrinding of crankshaft and line boring of bed plate
363	360	M/s SRF Limited	Madhya Pradesh	North	15.05.01	2270 KVA SKODA	Repair of CR Housings
364	361	Parasurampur Synthetics Ltd.	Rajasthan	North	24.05.01	Injectors of Wartsila	Repair of cylinder head
365	362	Modipon Fibres Co.	Uttar Pradesh	North	07.06.01	5 MW Wartsila	Repair of cylinder head
366	363	Maheshwari Mills	Uttar Pradesh	North	07.06.01	780 KVA WARTSILA	Grinding of crankshaft
367	364	Recron Synthetics Ltd.	Allahabad	West	09.06.01	2270 KVA SKODA	Repair of crankshaft
368	365	Nova Petrochemicals	Ahmedabad	West	12.06.01	Cyl. Head of Russian Engine	Metal Stitching of cylinder heads of Russian Engine
369	366	Rolls Royce Energy Systems India P.Ltd.	New Delhi	North	14.06.01	Valve Rotators	Repair of valve Rotators
370	367	Modipon Fibres Co.	U.P.	North	15.06.01	5 MW Wartsila Cylinder head	Repair of cylinder head
371	368	Indian Rayon & Ind. Ltd.	Gujarat	West	15.06.01	2270 KVA Skoda	Grinding of crankshaft
372	369	Indian Rayon & Ind. Ltd.	Gujarat	West	15.06.01	2270 KVA Skoda	Repair of Lower Crankcase, MJ Housings
373	370	Indian Rayon & Ind. Ltd.	Gujarat	West	15.06.01	2270 KVA Skoda	Repair of CR Housings
374	371	Maheshwari Mills Ltd.	U.P.	North	18.06.01	780 KVA Wartsila	Grindign of crankshaft
375	372	Shri Sahnmgavel Mills Ltd.	Tamil Nadu	South	22.06.01	1150 KVA SKL	Reconditioning of lower crankcase of 1150 KVA SKL D.G. Set
376	373	Recron Synthetics Ltd.	Allahabad	North	23.06.01	2270 KVA Skoda	Repair of lower crankcase
377	374	Arihant Spinning Mills	Malerkota, Punjab	North	26.06.01	4 MW Wartsila	Repair of cylinder head

	A	B	C	D	E	F	G
378	375	Wartsila NSD India Ltd.	New Delhi	North	05.07.01	5 MW Wartsila	Repair of cylinder head
379	376	National Aluminium Co. Ltd.	Nalconagar	East	07.07.01	TBTD3 Compressor	Rebuilding and grinding of crankshaft
380	377	Soma Textiles & Ind. Ltd.	Baramati, Pune	West	16.07.01	2270 KVA Skoda	Repair of camshaft
381	378	Madhusudan Industries Ltd.	Gandi'gr	West	18.07.01	860 KVA Skoda	Repair of crankshaft, L.C.C. and remetalling of corresponding bearings
382	379	Kirloskar Oil Engines	Nashik	West	21.07.01	K.Pielstick 6PA6LCL	Repair of crankshaft
383	380	M.V. Cotspin	New Delhi	North	26.07.01	350 Caterpillar	Metal Stitching of cylinder head
384	381	M.V. Cotspin	New Delhi	North	26.07.01	350 Caterpillar	Grinding , lapping & fitting of valve seat
385	382	Rico Auto Ind. Ltd.	Gurgaon	North	28.07.01	2270 KVA Skoda	Grinding/polishing of crankshaft
386	383	Rico Auto Ind. Ltd.	Gurgaon	North	28.07.01	2270 KVA Skoda	Repair of Engine Block
387	384	Srinath Ispat	Ghaziabad	North	28.07.01	1875 KVA Yanmar	Repair of crankshaft
388	385	SRF Ltd.	Madhya Pradesh	North	07.08.01	2270 KVA Skoda	Repair of CR Housings
389	386	Rana Papers Ltd.	Mfr'gar	North	11.08.01	1200 HP Allen	Reconditioning of crankshaft
390	387	Arham Spinning Mills	Rajasthan	North	20.08.01	6 MW Mirlees Blackstone D.G. Set	Repair of valves
391	388	National Steel Industries Ltd.	Indore	North	23.08.01	5 MW Russkie	Development of bush and thrust bearing of turbocharger (Exhaust End)
392	389	Hindusthan National Glass Ind. Ltd.	Haryana	North	25.08.01	860 KVA Skoda	Grinding of crankshaft
393	390	Nova Petrochemicals	Ahmedabad	West	28.08.01	Russian Engine	Metal Stitching of cylinder heads
394	391	Sree Rayalaseema Alkalies and Allied Chemicals Ltd.	Kurnool	South	01.09.01	6.2 MW Wartsila D.G. Set	Reconditioning of crankshaft
395	392	Northern Railway	Shakurbasti, Delhi	North	07.09.01	WDS 4 Loco	Reclamation of crankshaft
396	393	Arham Spinning Mills	Rajasthan	North	10.09.01	6 MW Mirlees Blackstone D.G.Set	Repair of valves
397	394	Priya Clay	Haryana	North	10.09.01	Daihatsu D.G. Set	Repair of crankshaft
398	395	Priya Clay	Haryana	North	10.09.01	Daihatsu D.G. Set	Remetalling of bearings
399	396	North Eastern Railway	Bareilly	North	12.09.01	YDMS4 Loco	Repair of camshaft
400	397	Arham Spinning Mills	Rajasthan	North	15.09.01	Mirlees Blackstone	Reconditioning of spare parts
401	398	Surya Roshni	B'garh (HR)	North	19.09.01	860 KVA Skoda	Repair of crankshaft and Metallizing of bearings
402	399	Ginni Filaments	Mathura	North	21.09.01	2525 KVA Watsila	Boring of cylinder head
403	400	Vikram Ispat Ltd.	M'rashtra	West	30.09.01	3250 KVA Skoda	Repair of crankshaft
404	401	Indian Rayon & Ind. Ltd.	Gujarat	West	12.10.01	2270 KVA Skoda	Grinding of crankshaft
405	402	Indian Rayon & Ind. Ltd.	Gujarat	West	12.10.01	2270 KVA Skoda	Repair of CR Housings
406	403	Recron Synthetics Ltd.	Allahabad	North	12.10.01	2270 KVA Skoda	Grinding of crankshaft
407	404	Recron Synthetics Ltd.	Allahabad	North	16.10.01	2270 KVA Skoda	Repair of Lower Crankcase
408	405	Bharat Electronics Ltd.	Kotdwara (U.P.)	North	19.10.01	860 KVA Skoda	Repair of crankshaft
409	406	Bharat Electronics Ltd.	Kotdwara (U.P.)	North	19.10.01	860 KVA Skoda	Metallising of bearing
410	407	Sukhjit Starch	Punjab	North	19.10.01	800 KVA Allen	Repair of crankshaft
411	408	Recron Synthetics Ltd.	Allahabad	North	25.10.01	2270 KVA Skoda	Line boring of Lower Crankcase
412	409	Rajasthan Spinning MillsLtd.	Rajasthan	North	05.11.01	860 KVA Skoda	Reconditioning of crankshaft & metallizing of bearings.
413	410	Modern Petrofils Ltd.	Baroda	West	21.11.01	860 KVA Skoda	Grinding of crankshaft
414	411	Modern Petrofils Ltd.	Baroda	West	21.11.01	860 KVA Skoda	Repair of Lower Crankcase
415	412	J.B. F. Industries	Silvasa (U.T.)	West	22.11.01	2270 KVA Skoda	Grinding of crankshaft
416	413	J.B. F. Industries	Silvasa (U.T.)	West	22.11.01	2270 KVA Skoda	Repair of Lower Crankcase
417	414	Ralson Industries Ltd.	Mandideep, Bhopal	North	29.11.01	1600 H.P. Deutz	Reconditioning of crankshaft
418	415	Ginni Filaments Ltd.	Mathura	North	30.11.01	860 KVA Skoda	Metal Stitching of cylinder head
419	416	Triveni Glass Ltd.	Allahabad	North	04.12.01	608 KVA Skoda	Grinding of crankshaft & remetallising of bearings

	A	B	C	D	E	F	G
420	417	Shree Siyaram Mills Ltd	Rakholi, silvasa U.T.	West	04.12.01	500 KVA Skoda	Grindign of crankshaft
421	418	Shree Siyaram Mills Ltd	Rakholi, silvasa U.T.	West	04.12.01	500 KVA Skoda	Metalling of MJ/CR bearing
422	419	Bhrikuti Pulp & Paper Nepal Ltd.	Nepal	Overseas	08.12.01	405 KVA Skoda	Grinding of crankshaft
423	420	Bhrikuti Pulp & Paper Nepal Ltd.	Nepal	Overseas	08.12.01	405 KVA Skoda	Remetallising of bearings
424	421	Recron Synthetics Ltd.	Allahabad	North	13.12.01	2270 KVA Skoda	Grindign of crankshaft
425	422	K.L. Concast Limited	Ghaziabad	North	13.12.01	2200 HP Mirrlees Blackstone	Repair of crankshaft
426	423	K.L. Concast Limited	Ghaziabad	North	13.12.01	580 HP Bergen	Repair of crankshaft
427	424	National Alluminium Co. Ltd.	Nalconagar	North	15.12.01	A3M Compressor shaft	Rebuilding and grinding of shaft
428	425	Nova Petrochemicals	Ahmedabad	West	24.12.01	Russian Engine	Metal Stitching of cylinder head
429	426	Deewan Tyre Ltd.	U.P.	North	26.12.01	860 KVA Skoda	Line boring
430	427	Owens Brockway India Ltd.	U.P.	North	08.01.2002	275 KVA Ruston	Repair of CR Housings/ Engine block
431	428	Tai Chon bang Textiles Ind. Ltd.	Ahmedbad	West	09.01.2002	2500 KVA SKL	Repair of CR Housings
432	429	TGBL	Vadora, Gujarat	West	09.01.2002	2270 KVA Skoda	Reconditioning of crankshaft, engine block and supply of undersize bearings
433	430	Surya Roshni	B'garh (HR)	North	21.01.2002	1000 KVA Russian	Repair of crankshaft and metallizing of bearings
434	431	Satna Cement	M.P.	North	28.01.2002	AEG 1500 W Motor	Development and Supply of bearings
435	432	Jubilant Organoys	U.P.	North	31.01.2002	2270 KVA Skoda	Metallising of lower crankcase and supply of spare parts
436	433	Jagajit Industries Limited	Punjab	North	02.02.2002	608 KVA Skoda	Grinding/polishing of crankshaft and remetalling of bearings
437	434	Shree Cement Limited	Rajasthan	North	13.02.2002	4 MW Deutz	Repair of camshafts
438	435	Rajshree Polyfils	Gujarat	West	13.02.2002	2270 KVA Skoda	Repair of alternator rotor shaft
439	436	Siyaram Silk Mills Ltd.	Silvasa (U.T.)	West	23.02.2002	500 KVA Skoda	Grinding of crankshaft and white metalling of MJ/CR bearings
440	437	SRF Ltd.	Bhind (M.P.)	North	23.02.2002	2270 KVA Skoda	Repair of lower crankcase
441	438	Arihant Multi - Fibres Limited	Biratnagar, Nepal	Overseas	26.02.2002	608 KVA Skoda	Reconditioning of crankshaft and remetallising of bearings
442	439	Recron Synthetics Ltd.	Allahabad	North	27.02.2002	2270 KVA Skoda	Repair of Lower Crankcase
443	440	National Fertilisers Limited	Panipat (HR)	North	28.02.2002	Air Compressor IGB - 101 A,B,C,D	Repair of crankshaft and supply of undersize bearings for Instt. Air Compressor
444	441	J.B.F. Industries Limited	Silvasa (U.T.)	West	28.02.2002	2270 KVA Skoda	Repair of CR Housings
445	442	Birla Corporation Limited	M.P.	North	02.03.2002	2650 KW Motor	Development and White metalling of bearings
446	443	KRBL Limited	U.P.	North	02.03.2002	1000 KVA Rumo	Repair of cylinder head
447	444	Nova Petrochemicals	Ahmedabad	West	14.03.2002	Russian Engine	Metal stitching of Cylinder head
448	445	Lauls Limited	Faridabad (HR)	North	16.03.2002	2050 KVA Mirrlees Blackstone	Supply of bearings
449	446	Triveni Spinning Mills (P) Ltd.	Nepal	Overseas	19.03.2002	860 KVA Skoda	Grindign of crankshaft, machining of bearing, line boring and remetaling of bearing
450	447	Magnum Power Generation Limited	Gurgaon	North	20.03.2002	6.3 MW Deutz	Grinding of crankshaft
451	448	Triveni Synthetics Yarn India (P) Ltd.	Nepal	Overseas	25.03.2002	405 KVA Skoda	Grinding of crankshaft, machining of bearing, line boring and remetalling of bearing
452	449	Magnum Power Generation Limited	Gurgaon	North	28.03.2002	6.3 MW Deutz	Line boring of Lower Crankcase
453	450	Magnum Power Generation Limited	Gurgaon	North	05.04.2002	6.3 MW Deutz	Repair of connecting rod housings
454	451	Pasupati Spinning and Weaving Mills	Rewari (HR)	North	08.04.2002	2.5 MW Deutz	Repair of bush
455	452	National Fertilisers Limited	Bhatinda, Punjab	North	10.04.2002	WHB and Subreactor flange	Development and Supply of seal weld gasket
456	453	Hindustan National Glass and Ind. Ltd.	B'garh (HR)	North	10.01.2002	4125 KVA Sulzer	Reconditioning of spare parts and overhauling of engine
457	454	National Fertilisers Limited	Naya Nangal, Punjab	North	13.04.2002	Impeller nut	Supply of shaft along with bearing lock and impeller nut
458	455	J.K. Cement Wiorks	Rajasthan	North	16.04.2002	5 MW Deutz	Reconditioning of crankshafts
459	456	Birla Corporation Limited	M.P.	North	17.04.2002	2650 KW Motor	Development and Supply of bearings
460	457	Gujrat Narmada Valley Fertilisers Co. Ltd.	Bharuch, Gujrarat	West	19.04.2002	Compressor Shaft	Rectification of crankshaft of C - 1001
461	458	National Alluminium Co. Ltd.	Angul, Orissa	East	20.04.2002	A3M Compressor shaft	Rebuilding and grinding of crankshaft

	A	B	C	D	E	F	G
462	459	SRF Ltd.	Bhind (M.P.)	North	23.04.2002	2270 KVA Skoda	Reconditioning of crankshaft and supply of undersize bearings
463	460	Ralsion Industries Ltd.	Bhopal	North	29.04.2002	1600 H.P. Deutz	Reconditioning of crankshaft and metallizing of bearing.
464	461	Ginni Filaments Ltd.	Chhata - Mathura Road	North	30.04.2002	2.2 MW Wartsila D.G. Set	Repairing of cylinder head
465	462	Diesel Component Works	Patiala	North	02.05.2002	-	Grinding and Polishing of Crank Boring Bar and Crank Boring bars
466	463	Recron Synthetics Ltd.	Allahabad	North	06.05.2002	2270 KVA Skoda	Grinding of crankshaft, Line boring of Lower Crankcase and supply of 1 mm undersize bearings
467	464	Soma Textiles & Ind. Ltd.	Pune	West	15.05.2002	2270 KVA Skoda	Grinding and polishing of crankshaft, repair of lower crankcase and repair of CR Housings.
468	465	Nova Petrochemicals	Ahmedabad	West	15.05.2002	Russian Engine	Metal stitching of cylinder head
469	466	Prasurampuriah Synthetics Ltd.	Rajasthan	North	15.05.2002	4 MW Wartsila	Reconditioning of cylinder liner
470	467	National Fertilisers Limited	Naya Nangal, Punjab	North	16.05.2002	Carbamate Pump	Development and Supply of spares
471	468	Magnum Power Generation Limited	Gurgaon	North	18.05.2002	Deutz D.G. Set	Repair of connecting rod housings
472	469	SPL Limited	B'garh (HR)	North	27.05.2002	1500 KVA Caterpillar D.G. Set	Repair of Engine Block and connecting rod housing
473	470	SPL Limited	B'garh (HR)	North	30.05.2002	1500 KVA Caterpillar D.G. Set	Repair of crankshaft, Lower Crankcase, Connecting rod and cylinder head
474	471	Tai Chon bang Textiles Ind. Ltd.	Ahmedabad	West	08.06.2002	SKL 9EVS 29/24 AL-2 Engines	Grinding of crankshaft
475	472	Orissa Polyfibres Ltd.	Dhenkanal (Orissa)	East	14.06.2002	2270 KVA Skoda	Repair of Engine Block
476	473	Orissa Polyfibres Ltd.	Dhenkanal (Orissa)	East	14.06.2002	2270 KVA Skoda	Polishing of crankshaft
477	474	Modi Vanaspati Mfg. Co.	Modinagar - U.P.	North	18.06.2002	860 KVA Skoda	Grinding of crankshaft
478	475	Nova Petrochemicals	Ahmedabad	West	24.06.2002	Russian Engine	Metal stitching of cylinder head
479	476	Indian Rayon & Ind. Ltd.	Gujarat	West	08.07.2002	2270 KVA Skoda	Grinding / Polishing of crankshaft
480	477	Indian Rayon & Ind. Ltd.	Gujarat	West	08.07.2002	2270 KVA Skoda	Repair of Engine Block
481	478	Indian Rayon & Ind. Ltd.	Gujarat	West	08.07.2002	2270 KVA Skoda	Repair of C.R. Housings
482	479	Devidayal Aluminium Industries Pvt. Ltd.	Ghaziabad	North	09.07.2002	1100 KVA SKL	Repair of crankshaft
483	480	Devidayal Aluminium Industries Pvt. Ltd.	Ghaziabad	North	09.07.2002	1100 KVA SKL	White metallizing of bearings
484	481	JCT Limited	Hoshiarpur - Punjab	North	09.07.2002	1450 KVA Skoda	Reconditioning of crankshaft and metallizing of bearing
485	482	TGBL	Vadora, Gujarat	West	09.07.2002	2270 KVA Skoda	Repair of camshaft
486	483	Winsome Yarn Ltd.	Chandigarh	North	09.07.2002	2.5 MW Pielstick	Balancing of Turbocharger
487	484	Nova Petrochemicals	Ahmedabad	West	17.07.2002	Russian Engine	Metal stitching of cylinder head
488	485	Good Year Limited	Ballabgarh	North	25.07.2002	C.I. Roll	Grinding of cylinder Roll
489	486	Recron Synthetics Ltd.	Allahabad	North	31.07.2002	2270 KVA Skoda	Repairing of LCC
490	487	Recron Synthetics Ltd.	Allahabad	North	31.07.2002	2270 KVA Skoda	Metal Stching of lower crank case
491	488	Soma Textiles & Ind. Ltd.	Baramati	West	01.08.2002	2270 KVA Skoda	Repairing of lower crank case
492	489	Soma Textiles & Ind. Ltd.	Baramati	West	01.08.2002	2270 KVA Skoda	Grinding & polishing of Crank shaft
493	490	Nova Petrochemicals	Ahmedabad	West	08.08.2002	2270 KVA Skoda	Metal Stching of Cylinder Head
494	491	Modipon Fibres	Modinagar - U.P.	North	08.08.2002	5MW Wartsila	Repair of CR Housing
495	492	SPL Limited	Bahadur Garh	North	10.08.2002	1500 KVA Caterpillar D.G. Set	Repair of Crank shaft
496	493	NALCO	Angul, Orissa	East	13.08.2002	TBTD-A3M Compressor	Rebuilding and grinding of Crank shaft
497	494	Recron Synthetics Ltd.	Allahabad	North	24.08.2002	2270 KVA Skoda	Repairing/boring of LCC
498	495	Atlas cycles industries	Sonipat	North	28.08.2002	500 kva skl	Repair of crankshaft
499	496	Wartsila India ltd	New Delhi	North	30.08.2002	6 MW Wartsila	Repair of cylinder head
500	497	Hindustan zinc ltd	Udaipur,Rajasthan	North	04.09.2002	5 mw Fuji	Reconditioning of Crankshaft
501	498	Paliwal Fibres ltd	Panipat (HR)	North	07.09.2002	825 kva Skoda	Metal Stching of Engine block
502	499	S.P.L. Ltd	Jhajjar,Hyr.	North	11.09.2002	1500 KVA Caterpillar D.G. Set	Repair of connecting rod and gudgeon pin
503	500	Arihant Spinning Mill	Melerkota	North	16.09.2002	SKL D.G.Set	Inspection of turbo charger

	A	B	C	D	E	F	G
504	501	Binani Zinc Ltd	Binanipuram,kerela	South	16.09.2002	5 mw Nigata D.G.Set	Repair of connecting rod
505	502	Shree Cement Limited	Ajmer,Rajasthan	North	19.09.2002	2.2 mw Wartsila D.G.Set	Inspection of crankshaft
506	503	Recron Synthetics Ltd.	Allahabad	North	28.09.2002	2270 KVA Skoda	Supply of std size bearing
507	504	Priya Clay Product Ltd	Jhajjar,Hyr.	North	28.09.2002	750 kva Daihatsu	Repair of Crankshaft
508	505	Madura Coats Limited	Madurai	North	04.10.2002	860 KVA Skoda	Grinding of crankshaft and line boring of LCC
509	506	Madura Coats Limited	Madurai	North	04.10.2002	860 KVA Skoda	White metalling of bearings
510	507	Aarvee Denims & Exports Ltd	Ahmedabad	West	07.10.2002	860 KVA Skoda D.G.Set	Grinding of crankshaft & Metal stitching of LCC
511	508	Aarvee Denims & Exports Ltd	Ahmedabad	West	07.10.2002	860 KVA Skoda D.G.Set	White metalling of bearings
512	509	vikram ispat	Raigad	West	16.10.2002	3250 KVA Skoda D.G.Set	Grinding of crankshaft and line boring of LCC
513	510	Recron SyntheticsLtd	Allahabad	North	03.10.2002	2270 KVA Skoda	Repairing of L.C.C.
514	511	Surya Roshni Ltd	Bahadurgarh	North	18.10.2002	1450 KVA Skoda	Grinding of crankshaft and line boring of LCC
515	512	Birla Corp.Ltd	Satna	North	19.10.2002	1750 KW Motor	Development and White metallizing of bearings
516	513	Soma Textile Ltd	Pune	West	31.10.2002	2270 KVA Skoda	Grinding of crankshaft & Metal stitching of LCC
517	514	G.N.F.C.	Bharuch,Gujarat	West	07.11.2002	C-2201engine	Repairing of crankshaft
518	515	Tractors india Ltd	sahibabad	North	10.11.2002	1500 KVA Caterpillar D.G. Set	Repairof connecting rod and gudgen Pin
519	516	G.S.F.C.	Surat	West	14.11.2002	2270 KVA Skoda	Grinding of crankshaft , line boring of LCC & supply of undersize bearing
520	517	N.F.L.Nangal	Nangal	North	16.11.2002	Cooling Tower	Development and Supply of spares
521	518	Kasta Sugar Ind	Lakhimpur, Kheri	North	18.11.2002	Yanmar D.G.Set	Repair of crankshaft
522	519	N.F.L.Nangal	Naya Nangal	North	20.11.2002	Carbamate Pump	Development and Supply of spares
523	520	Recron synthetics Ltd	Allahabad	North	25.11.2002	2270 KVA Skoda	Repair of crankshaft & Camshaft
524	521	Nova Petrochemical	Ahmedabad	West	28.11.2002	Russian Engine	metal stitching of cylinder head
525	522	J.B.F. Industries Limited	Silvasa (U.T.)	West	02.12.2002	2270 kva skoda	Repair of C.R. Housings
526	523	Modipon Fibres	Modinagar (UP)	North	29.11.2002	5 MW Wartsila	Repair of cylindr Heads
527	524	J.K. Cement Works	Nimbahera	North	03.12.2002	5.8 MW Sulzer	Line boring of Lower Crankcase
528	525	J.K. Cement Works	Nimbahera	North	17.12.2002	4 MW Fuji	repair of camshaft
529	526	Recron Synthetic ltd	Allahabad	North	26.12.2002	2270 KVA Skoda	Repair of lower crank case
530	527	Som Distillaries ltd	Bhopal	North	03.01.2003	Man B&W	In-situ grinding
531	528	J.K. Cement Works	Nimbahera	North	06.01.2003	5.8 MW Sulzer	repair of crankshaft
532	529	Paliwal Fibres ltd	Panipat (HR)	North	13.01.2003	825 kva skoda	Repair of crankshaft and lower crankcase
533	530	G.T.N Textile	Mahaboob Nagar(T.N)	South	14.01.2003	860 kva skoda	Repair of crankshaft
534	531	G.T.N Textile	Mahaboob Nagar(T.N)	South	14.01.2003	860 kva skoda	White metalling of bearings
535	532	Nova Petrochemicals	Ahmedabad	West	21.01.2003	100 kva Russian Engine	Metal Stitching of cylinder heads
536	533	Recron Synthetic ltd	Allahabad	North	05.02.2003	2270 kva skoda	repair of lower crankcase
537	534	Taj Mahal Hotel	New Delhi	North	08.02.2003	1050 kva Detroit	Remetalization of Alternator shaft
538	535	Sai Engineers & consultants	Gurgaon	North	08.02.2003	Bergen Engine	reonditioning of crankshaft
539	536	NFL,Nangal	Naya Nangal	North	24.02.2003	Piston Rod	Development and Supply of piston rod of recirculator
540	537	Oil India Ltd	Duliajan	East	26.02.2003	Ingersoll-Rand BPCL Gas Compressor	Repair of connecting rod
541	538	Shree Rajasthan Syntex ltd	Dungarpur	East	27.02.2003	2.5 MW Kirlosker Pielstick 9PAL LCL -	Rebuilding & Grinding of crank shafts
542	539	Apollo Fibres ltd	Hoshiarpur - Punjab	North	06.03.2003	1450 kva skoda	repair of crankshaft
543	540	J.K. Cement Works	Nimbahera	North	07.03.2003	4 MW Fuji D.G.Set	Reconditioning of crankshaft
544	541	Recron Synthetics ltd	Allahabad	North	07.03.2003	2270 kva skoda	Metal stitching of Main Journal Housing & line boring
545	542	Recron Synthetics ltd	Allahabad	North	07.03.2003	2270 kva skoda	Repair of lower crank case

	A	B	C	D	E	F	G
546	543	Recron Synthetics ltd	Allahabad	North	10.03.2003	2270 kva skoda	grinding of crank shaft
547	544	Nova Petro chemicals	Ahmedabad	West	10.03.2003	Russian Engine	metal stitching of cylinder heads
548	545	Hindustan National Glass	Bahadurgarh	North	22.03.2003	1450 kva skoda	Grinding of Crank shaft
549	546	Shri Velayudhaswamy Spinning Mills	Nagampatti(T.N)	South	22.03.2003	100 kva SKL D.G.Set	Reconditioning of crankshaft
550	547	Magnum Power Generation Ltd.	Gurgaon (Haryana)	North	08.04.2003	6.3 MW Deutz	Inspection of 6.3 MW Deutz Engine
551	548	Neolite Industries	Gurgaon (Haryana)	North	23.04.2003	320 kva Caterpillar	Metal stitching of Cylinder Head
552	549	Atlas Cycles Industries	Sonepat (Haryana)	North	25.04.2003	1000 kva Cummins	Repair of crankshaft
553	550	Vikram Ispat	Raigad (Maharashtra)	West	01.05.2003	3250 kva Skoda	Grinding of crankshaft, repair of MJ/CR housings
554	551	Som Distillaries Ltd	Bhopal, M.P.	North	05.05.2003	2.7 MW MAN	Repair of connecting rod
555	552	Recron Syn.Ltd	Allahabad	North	05.05.2003	2270 kva skoda	Repair of Lower Crankcase
556	553	Indian Rayon & Ind. Ltd.	Veraval, Guj	West	08.05.2003	2270 kva skoda	Repair of crankshaft ,LCC and supply of brg
557	554	Nova Petrochemicals	Ahmedabad	West	09.05.2003	1000 kva russian	Inspection of crankshaft
558	555	Jubilant Organoyo	Gajraula	North	10.05.2003	1450 kva skoda	Repair of crankshaft
559	556	Tata Chemicals	Babrala	North	14.05.2003	Compressor Shaft	Repair of crankshaft
560	557	Jaypee Rewa Cement	Rewa, M.P.	North	15.05.2003	6 MW Modi Mirlees Blackstone	Repair of crankshaft
561	558	Paswara Papers Ltd.	Mohiuddinpur,U.P.	North	15.05.2003	1100 kva SKL	Repair of crankshaft
562	559	Recron Synthetics	Allahabad, UP	North	22.05.2003	2270 kva Skoda	Repair of crankshaft
563	560	Jubilant Organoyo	Jyotiba Phule Nagar, UP	North	24.05.2003	1450 kva Skoda	Metal stitching of lower crank case
564	561	Modern Petrofils Ltd.	Baroda, Gujarat	West	27.05.2003	860 kva Skoda	Repair of crankshaft
565	562	Shree Rajeshwari Mills	Vellor	South	27.05.2003	860 kva Skoda	Repair of crankshaft
566	563	Grasim Inds.	Jodhpur, Raj	North	29.05.2003	3.1 MW Mirlees Blackstone	Inspection of connecting rod
567	564	Rajasthan Spinning	Gulabpura, Rajasthan	North	30.05.2003	860 kva Skoda	Repair of crankshaft
568	565	National Fertilizers Ltd.	Guna, M.P.	North	07.06.2003	Compressor Shaft	Rebuilding and grinding of crankshaft
569	566	Hindustan Vidyut Ltd.	Faridabad (HR)	North	26.06.2003	860 kva Skoda	Reconditioning of crankshaft
570	567	Paswara Papers Ltd.	Mohiuddinpur,U.P.	North	27.06.2003	1100 kva SKL	Grinding/Polishing of crankshaft
571	568	Parasurampuriah Intl.	Indore	North	30.06.2003	4 MW Wartsila	Repair of crankshaft
572	569	Appollo Fibres Ltd.	Hoshiarpur - Punjab	North	30.06.2003	1450 kva Skoda	Repair of crankshaft
573	570	Appollo Fibres Ltd.	Hoshiarpur - Punjab	North	05.07.2003	1450 kva Skoda	Repairing of camshaft & upper block
574	571	Narendra Press-Tech	New Delhi	North	16.07.2003	Mechanical Press	Grinding of crankshaft
575	572	Hindustan Aeronautics Ltd.	Bangalore	South	28.07.03	1150 KVA SKL	Grinding of Crankshaft
576	573	Diesel Components Works	Patiala	North	29.07.03	Pama boring machine	Stratening,grinding & polishing of cam boring bars
577	574	Creative Dyeing & Printing	Faridabad (HR)	North	31.07.03	Man DG Set	Repair of Crankshaft
578	575	Hindustan National Glass	Bahadurgarh (HR)	North	02.08.03	4125 KVA Sulzer	Inspection of crankcase
579	576	Shree Rajasthan Syntex Ltd.	Dungarpur, Rajasthan	North	05.08.03	2.5 MW Kirloskar Pielstick	Inspection of connecting rod
580	577	Bindlas Duplex Ltd.	Muzaffarnagar, UP	North	25.08.03	1450 KVA Skoda	On-Site Grinding of Crankshaft
581	578	Paswara Papers Ltd.	Mohiuddinpur, UP	North	28.08.03	1100 KVA SKL	Grinding of Crankshaft
582	579	Rajesh Aluminium Ind. P. Ltd.	Birgunj, Nepal	Overseas	04.09.03	405 KVA Skoda	Repair of crankshaft & supply of bearings
583	580	Orissa Polyfibres Ltd.	Dhenkanal, Orissa	East	10.09.03	2270 KVA Skoda	Repair of Lower Crankcase
584	581	Recron Synthetics Ltd.	Allahabad, UP	North	13.09.03	2270 KVA Skoda	Repair of Lower Crankcase & supply of undersize bearings
585	582	Modern Petrofils Ltd.	Baroda, Gujarat	West	30.09.03	2270 KVA Skoda	Repair of crankshaft & engine block
586	583	Consolidated Coin Co.	Faridabad (HR)	North	06.10.03	Man D.G. Set	Repair of connecting rod housings
587	584	Birla Corp.Ltd	Satna, M.P.	North	09.10.03	Metallizing of bearing	Development and Supply of white metal bearing

	A	B	C	D	E	F	G
588	585	Sriba Inds. Ltd.	Hyderabad, A.P.	South	11.10.03	3480 KW Caterpillar	Repair of crankshaft & connecting rod
589	586	Ravalgaon sugar Farm Ltd	Nasik , Mah	West	23.10.03	Mirlees Blackstone	Repair of Crankshaft Mirlees Blackston DG set
590	587	BPCL	Allahabad	North	01.11.03	Compressor CrankShaft	Rebuilding and grinding of compressor crankshaft
591	588	Sriba Inds. Ltd.	Hyderabad, A.P.	South	04.11.03	3480 KW Caterpillar	Inspection & Repair of LCC
592	589	Recron Synthetics Ltd	Allahabad	North	05.11.03	2270 KVA Skoda	Repair of LCC
593	590	Aarvee Denims & Exports Ltd	Ahmedabad	West	13.11.03	500 KVA Skoda D.G.Set	Repair of Crankshaft
594	591	Ralson Industries Ltd.	Ludhiana, Pb.	North	15.11.03	2.7 MW Pielstick	Repair of crankshaft, engine block & connecting rod housings
595	592	Modern Petrofils Ltd.	Baroda	West	26.11.03	2270 KVA SKODA	Repair of Crankshaft, Engine block & Metal stitching of Main Journal Housing
596	593	Hindustan National Glass	Bahadurgarh	North	03.12.03	4125 KVA Sulzer	Repair of crankshaft
597	594	Wartsila India ltd	New Delhi	North	09.12.03	Wartsila	Machining of cylinder heads and liners
598	595	Good Year Limited	Ballabgarh	North	12.12.03	C.I. Roll	Repair of C.I. Roll
599	596	K.L. Concast Limited	Ghaziabad	North	13.12.03	1100 KVA SKL	Grinding of crankshaft
600	597	SRF Ltd.	Bhind (M.P.)	North	16.12.03	2270 KVA	Reconditioning, line boring & metal stitching of LCC
601	598	Sriba Inds. Ltd.	Hyderabad, A.P.	South	19.12.03	3480 KW Caterpillar	Repair of crankshaft
602	599	Tai Chon bang Textiles Ind. Ltd.	Ahmedabad	West	22.12.03	2500 KVA SKL	Repair of crankshaft
603	600	Recron Synthetics Ltd	Allahabad	North	23.12.03	2270 KVA CKD	Repair of LCC
604	601	Shree Cement Limited	Ajmer,Rajasthan	North	23.12.03	2.3 MW Wartsila	Inspection of MJ & CR Pins
605	602	NFL, Panipat	Panipat (HR)	North	24.12.03	Ammonia Feed Pump	Matching of crankcase
606	603	Good Year Limited	Ballabgarh	North	12.01.04	C.I. Roll	Repair of C.I. Roll
607	604	Hindustan zinc ltd	Chittorgarh (Raj.)	North	14.01.04	5 MW Allen	Line boring of LCC
608	605	Shree Rajasthan Syntex	Dungarpur	East	14.01.04	2.5 MW Kirloskar Pielstick	Inspection of counter weight bolts
609	606	Recron Synthetics Ltd	Allahabad	North	17.01.04	2270 KVA CKD	Repair of LCC
610	607	India Cements Ltd	Tirunelveli (T.N)	South	20.01.04	4 MW Daihatsu	Repair of crankshaft
611	608	Kirloskar Oil Engines Ltd.	Nashik , Mah	West	28.01.04	2.5 MW Kirloskar Pielstick	Balancing of crankshaft
612	609	Kirloskar Oil Engines Ltd.	Nashik, Mah	West	28.01.04	2.5 MW Kirloskar Pielstick	Repair of crankshaft
613	610	Kirloskar Oil Engines Ltd.	Nashik, Mah	West	28.01.04	2.5 MW Kirloskar Pielstick	Polishing of crankshaft
614	611	Kirloskar Oil Engines Ltd.	Nashik, Mah	West	28.01.04	2.5 MW Kirloskar Pielstick	Inspection of MJ & CR Pins
615	612	Indian Rayon & Ind. Ltd.	Veraval, Guj	West	03.02.04	2270 KVA CKD	Repair of CR Housings
616	613	Parasrampuriah Synthetics Ltd	Indore(MP)	North	07.02.04	4 MW Wartsila	Repair of crankshaft
617	614	TIL Ltd.	sahibabad	North	10.02.04	500 KVA CAT	Repair of LCC
618	615	Sangam Spinners	Bhilwara (Raj)	North	11.02.04	3.8 MW Man B&W	Repairing of crankshaft and line boring of engine block
619	616	Winsome Yarn Ltd.	Patiala	North	14.02.04	2.5 Kirloskar Pielstick	Repair of crankshaft
620	617	Royal Ceramics	Nigeria	Overseas	19.02.04	860 KVA CKD	Insitu Line Boring of MJ
621	618	Parasrampuriah Synthetics Ltd	Alwar (Raj.)	North	21.02.04	4 MW Wartsila	Repair of Engine Block
622	619	SRF Ltd.	Bhind (M.P.)	North	24.02.04	2270 KVA CKD	Repair of crankshaft
623	620	SRF Ltd.	Bhind (M.P.)	North	24.02.04	2270 KVA CKD	Boring & Metal Stitching of MJ Housings
624	621	Parasrampuriah Synthetics Ltd	Alwar (Raj.)	North	02.03.04	4 MW Wartsila	Regrinding of crankshaft
625	622	Recron Synthetics Ltd	Allahabad	North	09.03.04	2270 KVA CKD	Repair of LCC, Metal Stitching of MJ housings
626	623	Century Yarn	Khargone, M.P.	North	10.03.04	1525 KVA CKD	Repair of crankshaft
627	624	K.L. Steel	Ghaziabad	North	11.03.04	2500 KVA Deutz	Reconditioning of Crankshaft
628	625	K. L. Steel	Ghaziabad	North	11.03.04	2500 KVA Deutz	Repair of Lower Crank Case
629	626	Brahmaputra Valley Fertilizer Corpn. Ltd.	Namrup	East	13.03.04	High pressure Peroni Pump	Repair of crankshaft & supply of bearings

	A	B	C	D	E	F	G
630	627	Good Year Limited	Ballabgarh	North	15.03.04	Tyre Curing Press Machine	On-site Machining of M.J. Housings of Tyre Curing Press Machine
631	628	Hindustan zinc ltd	Chittorgarh (Raj.)	North	17.03.04	5 MW Allen DG Set	Repair of Lower Crank Case
632	629	Indian Rayon	Veraval, Guj	West	23.03.04	2270 KVA Skoda	Repair of C.R. Housings
633	630	Hooghly Mills Co. Ltd.	Kolkata	East	07.04.04	860 KVA Skoda	Repair of Crankshaft
634	631	Rajashree Polyfil Ltd.	Bharuch	West	08.04.04	2270 KVA Skoda	Repair of engine block
635	632	Magnum Papers Ltd.	Ghaziabad	North	21.04.04	1200 KVA Caterpillar	Insitu grinding
636	633	Master M.V Ocean Hope	Haldia	East	21.04.04	Daihatsu 6PSHT-26D D.G. Set	Insitu grinding
637	634	JB Daruka Papers Ltd.	Sitapur, UP	North	26.04.04	Mirlees Blackstone	Repair of crankshaft, LCC, Connecting Rod
638	635	Tag Sealogistics Ltd.	Mumbai	West	26.04.04	KVMB-12 Burgen DG Set	Repair of crankshaft, engine block, connecting rod housings, cylinder liner
639	636	Recron Synyhetics Ltd.	Allahabad	North	1.05.04	2270 Kva Skoda	Repair of Lower crankcase,Metal stitching of M.J.Housing
640	637	S.R.F Ltd	Mallan pur	North	1.05.04	2270 KVA SKODA	Repair of crankshaft
641	638	Reliance India Ltd.	Surat	West	8.05.04	DS-3 Housing Bore	Insitu Boring
642	639	Neptunus Power Plant	Mumbai	West	26.05.04	2500 KVA SKL D.G.Set	InsituGrinding ofcrankshaft
643	640	Madhumilan Industries	Rajgarh	North	02.06.04	1375kva DaihatsuD.G.Set	Inspection of Engine block &connecting rod
644	641	Micro Inks Ltd.	Vapi	West	04.06.04	7M.W12TM 410 SulzerD.G. Set	Repair of crankshaft &line boring of engine bblock
645	642	Tractor India Ltd.	Ghaziabad	North	10.06.04	1250kva CaterpillarD.G.Set	Inspection ofConnecting Rod
646	643	Rajasthan Spng.&Wvg.Mills	Udaypur	North	15.06.04	1550 kva skoda D.G.Set	Repairing of Crankshaft,metallizing of bearing and line boring
647	644	Recron Synthetics Ltd.	Allahabad	North	15.06.04	2270kva CKD	Repairing of Crankshaft
648	645	Recron Synthetics Ltd.	Allahabad	North	19.06.04	2270kva CKD	Repairing of Lower crankcase of DG No. 11 & Metalstitching of M.J.Housing
649	646	Recron Synthetics Ltd.	Allahabad	North	28.06.04	2270 Kva CKD	Repairing of Lower crankcase of DG No.6 & Metalstitching of M.J.Housing
650	647	Rajshree Polyfils	Bharuch	West	01.07.04	2270 KVA Skoda	Repair of LCC
651	648	Rajshree Polyfils	Bharuch	West	01.07.04	2270 KVA Skoda	Polishing of crankshaft
652	649	K. L. Steel	Ghaziabad	North	03.07.04	2500 KVA Deutz	Repair of LCC
653	650	Wartsila India ltd	Noida	North	08.07.04	7 MW Wartsila	Inspection of connecting rod
654	651	Sanghi Industries Ltd.	Kutch	West	08.07.04	11 MW Mirlees Blackstone	Inspection of crankshaft
655	652	V. S. Dempo & Co. Pvt. Ltd.	Panaji, Goa	South	10.07.04	Daihatsu 8PSHTC-26 M	On site re-conditioning of Crank Pin
656	653	Vikram Ispat	Raigad, Mah.	West	10.07.04	3250 KVA Skoda D.G.Set	Inspection of LCC, MJ Housings by Easy Laser Equipment
657	654	Asahi India Glass Ltd.	Rewari (HR)	North	20.07.04	Mirlees Blackstone	Line boring of LCC
658	655	H.P. Cotton Mills	New Delhi	North	23.07.04	1450 KVA Skoda	Repair of Rotor shaft
659	656	Krishna Knitwear Tech Ltd.	Silvasa (U.T.)	West	09.08.04	1.6 MW Anglo Belgian	Inspection of Crankshaft
660	657	Uni Klinger Limited	Pune	West	10.08.04	Calender Roll	Inspection of Calender Roll
661	658	V. S. Dempo & Co. Pvt. Ltd.	Panaji, Goa	South	12.08.04	Daihatsu 8PSHTC-26 M	Reconditioning of connecting rods
662	659	Larsen & Toubro Ltd.	Anantapur	South	14.08.04	Man B & W	Inspection of Crankshaft
663	660	Tai Chon bang Textiles Ind. Ltd.	Ahmedabad	West	27.08.04	2500 KVA SKL 9EVS 29/24 AL-2	Repair of Crankshaft
664	661	Recron Synthetics	Allahabad	North	28.08.04	2270 KVA Skoda	Repair of LCC
665	662	Satna Cement	Satna	North	04.09.04	Hollow Shaft	Inspection of Hollow shaft
666	663	ONGC Ltd.	Mumbai	West	04.09.04	2100 KW General Motor	Inspection of DG set
667	664	Kirloskar Oil Engines Ltd.	Nashik	West	04.09.04	Kirloskar Pielstick	Making of radius of crank shaft on site
668	665	Shree Rajasthan Syntex Ltd.	Dungarpur	East	14.09.04	2.5MW Kirloskar Pielstick	Repair and reconditioning of Crankshaft
669	666	Indian Oil Corpn. Ltd.	Chaksu	North	20.09.04	Allen Type-8S37E	Reconditioning of crankshaft
670	667	Shah Alloys Ltd.	Ahmedabad	West	21.09.04	18PC2.2 Pielstick	Grinding of crankshaft and line boring of LCC
671	668	Vikram Ispat	Raigad	West	25.09.04	3250 KVA Skoda	Repair of Crankshaft, M.J. & C.R. Housing

	A	B	C	D	E	F	G
672	669	Soma Textiles	Baramati	West	05.10.04	2270 Kva Skoda	Honing & boring of Cylinder Liners
673	670	National Fertilizers Ltd.	Guna, M.P.	North	06.10.04	Ammonia Feed Pump	Repair of Crankshaft of Ammonia Feed Pump
674	671	Leo Shipping Co. Ltd.	Bangkok	Overseas	07.10.04	Daihatsu 6PSHT-26D D.G. Set	Insitu grinding
675	672	Indraprastha Gas Ltd.	New Delhi	North	13.10.04	Safe Compressor	Remetalling and grinding of crankshaft
676	673	Spintex Mill	Nigeria	Overseas	16.10.04	1450 Kva Skoda	Metal Stitching and boring of bottom portion of the liner seating area of upper crank case
677	674	Shah Alloys Ltd.	Ahmedabad	West	21.10.04	18PC2.2 Pielstick	Grinding of crankshaft
678	675	Amse-Palam	New Delhi	North	26.10.04	CumminsDG Set	Repair of crankshaft
679	676	Rajshree Polyfils	Bharuch	West	28.10.04	2270 Kva Skoda	Polishing of crank shaft Repair of Lower Crank Case & Honing boring of Cylinder liners
680	677	Rajshree Polyfils	Bharuch	West	28.10.04	2270 kva Skoda	Metal Stitching of main journal housing
681	678	Paswara Papers Ltd.	Meerut	North	29.10.04	1100 Kva SKL DG Set	Grinding of crankshaft
682	679	Recron synthetics Ltd.	Allahabad	North	15.11.04	2270 Kva Skoda DG set	Repair of Lower Crank Case
683	680	Oil India Ltd	Assam	East	17.11.04	Compressor CrankShaft 400 Hp	Repair of crankshft
684	681	Asahi India Glass Ltd.	Rewari (HR)	North	17.11.04	4.2Mw Mirlees Blackstone DG set	Repair of Cylinder Head
685	682	Amse-Palam	New Delhi	North	23.11.04	Cummins DG Set	Repair of Crankshaft and crank case
686	683	Krishna Knitwear Tech Ltd.	Silvasa (U.T.)	West	25.11.04	1.6 MW Anglo Belgian	Repair of Crankshft, Connecting Rod and Cylinder Liners
687	684	Recron synthetics Ltd	Allahabad	North	03.12.04	2270 Kva Skoda	Honing & boring of Cylinder Liners on site
688	685	Southern Energy Development Corporation Ltd	Tiruvarur (TN)	South	06.12.04	2500 Kva Caterpillar DG set	Line Boring of Engine Block on site
689	686	Uni Klingler Limited	Pune	West	06.12.04	CI Roll	Grinding of Calender Roll
690	687	Chidambaram Shipcare Pvt. Ltd.	Mumbai	West	07.12.04	Daihatsu	Insitu grinding
691	688	J. K. Cement Works	Nimbahera	North	07.12.04	Fuji 12VH32	Reconditioning of Crankshaft
692	689	Soma Textiles Ltd.	Baramati	East	07.12.04	2270 KVA Skoda	Honing and boring of Cylinder Liners
693	690	Prism Cement Ltd.	Satna	North	08.12.04	18V32 Wartsila	Inspection of crankshaft
694	691	Chidambaram Shipcare Pvt. Ltd.	Mumbai	West	11.12.04	Daihatsu	Insitu grinding
695	692	Recron Synthetics Ltd.	Allahabad (U.P)	North	15.12.04	2270 KVA Skoda	Grinding of crankshaft
696	693	Amse-Palam	New Delhi	North	20.12.04	KOEL	Repair of Crankshaft
697	694	Ralson Industries Ltd.	Ludhiana, Pb.	North	22.12.04	Mirlees Blackstone	Insitu grinding
698	695	Modern Petrofils Ltd.	Baroda	West	04.01.05	2270 KVA Skoda	Repair of Engien Block
699	696	National Engg. Ind. Ltd.	Jaipur	North	10.01.05	860 KVA Skoda	Repair of Crankshaft
700	697	Martek Engineering Wroks	Mumbai	West	11.01.05	2700 HP MWM	Inspection of Crankshaft, Engine Block, Cylinder Liners
701	698	Flex Industries Ltd.	Noida (U.P)	North	11.01.05	2.5MW Kirloskar Pielstick	Repair of Engine Block & Rebuilding of MJ Housing NO.1
702	699	Amse-Palam	New Delhi	North	14.01.05	KOEL	Repair of LCC
703	700	Recron Synthetics Ltd.	Allahabad (U.P)	North	17.01.05	2270 KVA Skoda	On site Honing and boring of Cylinder Liners of DG No.8
704	701	Recron Synthetics Ltd.	Allahabad (U.P)	North	17.01.05	2270 KVA Skoda	On site Honing and boring of Cylinder Liners DG No.9
705	702	Siyaram Silk Mills Ltd.	Silvasa (U.T.)	West	02.02.05	608 KVA Skoda	Repair of Crankshaft
706	703	National Aluminium Co. Ltd.	Nalco Nagar (Orissa)	East	09.02.05	TBTD-A3M Compressor	Repair of Crankshaft
707	704	Uttam Galva Steels Ltd.	Mumbai	West	09.02.05	3.5MW Ruski	Inspection of DG set
708	705	Modipon Fibres Ltd.	Modi Nagar (UP)	North	11.02.05	5 MW Wartsila	Repair of Connecting Rods
709	706	Uni Klingler Limited	Pune	West	11.02.05	CI Roll	Onsite lapping
710	707	Amse-Palam	New Delhi	North	14.02.05	KOEL	Repair of Crankshaft
711	708	Orissa Polyfibres Ltd.	Dhenkanal, Orissa	East	18.02.05	2270 KVA Skoda	Repair of Crankshaft, Engine Block, Connecting Rod Housings, and Cylinder Liners
712	709	Modipon Fibres Ltd.	Modi Nagar (UP)	North	19.02.05	5 MW Wartsila	Repair of Connecting Rods
713	710	Recron Synthetics Ltd.	Allahabad (U.P)	North	23.02.05	2270 KVA Skoda	Insitu grinding of 1 No. C.R. Pin

	A	B	C	D	E	F	G
714	711	Recron Synthetics Ltd.	Allahabad (U.P)	North	26.02.05	2270 KVA Skoda	Grinding of Crankshaft
715	712	Indian Oil Corpn. Ltd.	Rajkot	West	26.02.05	Allen MP3	Polishing of Crankpin
716	713	Recron Synthetics Ltd.	Allahabad (U.P)	North	3.03.05	2270 KVA Skoda	Repair of LCC of DG No.1
717	714	Chidambaram Shipcare Pvt. Ltd.	Mumbai	West	09.03.05	6PSHT-26D Daihatsu	Insitu grinding of 1 No. C.R. Pin
718	715	Lucky Marine Service	Kutch	West	21.03.05	6PSHTB-26D Daihatsu	Insitu grinding of DG Set 2 & 3
719	716	Creative Dyeing & Printing	Faridabad (HR)	North	22.03.05	630 KVA MAN	Repair of crankshaft
720	717	SRF Ltd.	Bhind (M.P.)	North	23.03.05	2270 KVA Skoda	Repair of Crankshaft, LCC
721	718	Rajashree Polyfil Ltd.	Bharuch	West	25.03.05	2270 KVA Skoda	Repair of Crankshaft, LCC & Cylinder Liners
722	719	Taichong bang Textiles Ind. Ltd.	Ahmedabad	West	28.03.05	2500 KVA SKL	Repair of Crankshaft, LCC & Connecting Rod
723	720	Indian Oil Corpn. Ltd.	Sidhpur	West	30.03.05	Allen Engine	Repair of Engine Block
724	721	Kirloskar Oil Engines Ltd.	Pune	West	30.03.05	Kirloskar Pielstick	Repair of Cylinder Liners
725	722	Recron Synthetics Ltd.	Allahabad	North	31.03.05	2270 KVA Skoda	Repair of LCC
726	723	Recron Synthetics Ltd.	Allahabad (U.P)	North	31.03.05	2270 KVA Skoda	Grinding of Crankshaft
727	724	Orient Cement	Adilabad	South	05.04.05	4 MW Daihatsu	Grinding of Crankshaft, repair of engine block, rebuilding of Main Journal & Connecting Rod
728	725	Recron Synthetics Ltd.	Allahabad	North	14.04.05	2270 KVA Skoda	Repair of Cylinder Liners
729	726	Amse-Palam	New Delhi	North	15.04.05	KOEL	Repair of Crankshaft
730	727	Uni Klinger Limited	Pune	West	19.04.05	Calendar Roll	Grinding of Top & Bottom Roll
731	728	Recron Synthetics Ltd.	Allahabad	North	21.04.05	2270 KVA Skoda	Repair of LCC
732	729	AGR Steel Strips Pvt. Ltd.	Dharuhera	North	26.04.05	1250 KVA Sulzer	Grinding of Crankshaft
733	730	Indraprastha Gas Ltd.	New Delhi	North	29.04.05	Waukesha	Repair of Connecting Rod Housings, Engine Block and Rebuilding & Grinding of Crankshaft
734	731	Magnum Power Generation Ltd.	Gurgaon	North	03.05.05	6 MW Deutz	Repair of Crankshaft
735	732	Indian Rayon Ind. Ltd.	Veraval, Guj	West	06.05.05	2270 KVA Skoda	Repair of crankshaft, engine block & connecting rod housings of DG No. B
736	733	Rajasthan Spinning & Weaving Mills	Rishabhdev	North	09.05.05	1525 KVA SKODA	Repair of Crankshaft
737	734	Indian Rayon Ind. Ltd.	Veraval, Guj	West	25.05.05	2270 Kva Skoda	Repair of Crankshaft, Engine Block, Connecting Rod Housings and rebuilding of C.R. Pin No.4 of DG
738	735	J.P. Bela Plant	Rewa	North	13.06.05	Man B & W	Repair of Crankshaft, Cylinder Liners and Connecting Rods
739	736	Hindustan National Glass & Ind. Ltd.	Bahadurgarh	North	14.06.05	1200 KVA Mirrlees Blackstone	Repair of Crankshaft
740	737	Indraprastha Gas Ltd.	New Delhi	North	27.06.05	Caterpillar	Repair of Crankshaft, Engine Block, C.R Housings
741	738	Lucky Marine Service	Kutch	West	06.07.05	Daihatsu	Insitu grinding of C.R Pin No.5
742	739	Indraprastha Gas Ltd.	New Delhi	North	06.07.05	Caterpillar	Repair of Crankshaft, Engine Block, C.R Housings
743	740	Kirloskar Oil Engines Ltd.	Pune	West	12.07.05	Kirloskar Pielstick	Repair of Cylinder Liners
744	741	Recron Synthetics Ltd.	Allahabad	North	14.07.05	2270 KVA Skoda	Repair of Cylinder Liners
745	742	Jindal Saw Ltd.	Kutch	West	18.07.05	5.8MW Sulzer	Repair of Crankshaft
746	743	V. S. Dempo & Co. Pvt. Ltd.	Goa	South	22.07.05	Daihatsu	Reconditioning of C.R. Housings
747	744	Paswara Papers Ltd.	Meerut	North	26.07.05	1100 Kva SKL DG Set	Grinding of Crankshaft
748	745	Recron Synthetics Ltd.	Allahabad	North	03.08.05	2270 KVA Skoda	Repair of Crankshaft, Engine Block
749	746	Winsome Yarn Ltd.	Patiala	North	04.08.05	2.5 MW Kirloskar Pielstick	Repair of Cylinder Head
750	747	Indian Oil Corpn. Ltd.	Rajkot	West	09.08.05	Allen	Repair of Crankshaft
751	748	DCW	Patiala	North	09.08.05	MAC	Repair of crankshaft
752	749	Shree Sindhuja Sugar Ind. Ltd.	Sitapur, UP	North	09.08.05	MAN 500 HP	Grinding of Crankshaft
753	750	ONGC Ltd.	Mumbai	West	12.08.05	General Motor	Overhauling and repair
754	751	V. S. Dempo & Co. Pvt. Ltd.	Goa	South	13.08.05	Daihatsu	Reconditioning of C.R. Housings
755	752	Leo Shipping Co. Ltd.	Tuticorin	South	22.08.05	Daihatsu	Insitu grinding of Crankshaft

	A	B	C	D	E	F	G
756	753	Recron Synthetics Ltd.	Allahabad	North	22.08.05	2270 KVA Skoda	Insitu grinding of Crankshaft
757	754	Leo Shipping Co. Ltd.	Bangkok	Overseas	30.08.05	Daihatsu	Insitu grinding of Crankshaft
758	755	SRF Ltd.	Bhind (M.P.)	North	31.08.05	2270 KVA Skoda	Repair of crankshaft and lower crankcase
759	756	Indian Rayon Ind. Ltd.	Veraval, Guj	West	01.09.05	2270 KVA Skoda	Repair of C.R. Housings
760	757	SRF Ltd.	Bhind (M.P.)	North	03.09.05	2270 KVA Skoda	Repair of Cylinder Liners
761	758	Indian Oil Corpn. Ltd.	Guwahati	West	05.09.05	Compressor	Reconditioning of Crankshaft
762	759	Lucky Marine Service	Kutch	West	06.09.05	Daihatsu	Insitu grinding of Crankshaft
763	760	Amse-Palam	New Delhi	North	06.09.05	Ruston	Repair of Crankshaft
764	761	Indraprastha Gas Ltd.	New Delhi	North	10.09.05	Waukesha	Repair of Crankshaft, Engine Block and C.R. Housings
765	762	Ganga International	New Delhi	North	06.09.05	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
766	763	Paswara Papers Ltd.	Meerut	North	12.09.05	1100 Kva SKL DG Set	Grinding of Crankshaft
767	764	VS Dempo	Panaji	South	13.09.05	Dahaitsu	Reconditioning of C.R. Housings
768	765	Sanghi Cement	Kutch , Gujrat	West	14.09.05	11.33 MW MAN	Repair of C.R. Housings
769	766	Indraprastha Gas Ltd.	New Delhi	North	19.09.05	Compressor	repair of compressor shaft
770	767	ISGEC	Yamunanagar	North	23.09.05	shaft	grinding of eccentric shaft
771	768	ISGEC	Yamunanagar	North	01.10.05	shaft	grinding of eccentric shaft
772	769	Indian Rayon Ind. Ltd.	Veraval, Guj	West	14.10.05	2270 KVA Skoda	Grinding/polishing of Crankshaft
773	770	Indraprastha Gas Ltd.	New Delhi	North	17.10.05	Waukesha	Repair of Crankshaft, Engine Block and C.R. Housings
774	771	Recron syntheitic	Allahabad	North	25.10.05	2270 KVA Skoda	Repair of Engine Block
775	772	KL Steel Ltd	Ghaziabad	North	26.10.05	1200 HP MAN	Repair of Crankshaft
776	773	Recron syntheitic	Allahabad	North	31.10.05	2270 KVA Skoda	Honing and boring of Cylinder Liners
777	774	SRF Ltd.	Bhind, MP	North	31.10.05	2270 KVA Skoda	Insitu polishing of crankshaft
778	775	SRF Ltd.	Bhind, MP	North	05.11.05	2270 KVA Skoda	Repair of Engine Block

	A	B	C	D	E	F	G
779	776	Indraprastha Gas Ltd.	New Delhi	North	08.11.05	Compressor	Repair of piston rods
780	777	Indraprastha Gas Ltd.	New Delhi	North	08.11.05	Waukesha	Polishing of Crankshaft
781	778	Indraprastha Gas Ltd.	New Delhi	North	08.11.05	Waukesha	Polishing of Crankshaft
782	779	Indraprastha Gas Ltd.	New Delhi	North	08.11.05	Waukesha	Polishing of Crankshaft
783	780	Ganga International	New Delhi	North	08.11.05	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
784	781	MV Ispat Star	Belapur, Mumbai	West	09.11.05	Daihatsu	Insitu grinding of Crankshaft
785	782	Winsome Yarn Ltd.	Patiala	North	10.11.05	2.5 MW Kirloskar Pielstick	Repair of Cylinder Liners
786	783	Vikram Ispat Ltd	Raigarh, Maharastra	West	12.11.05	3250 KVA Skoda	Repair of C.R. Housings
787	784	Magnum Power Generation Ltd.	Gurgaon	North	15.11.05	Deutz	Repair of engine block
788	785	TIL Ltd	Ghaziabad	North	16.11.05	1000 KVA Caterpillar	Rapair of crankshaft
789	786	Recron Synthetics Ltd.	Allahabad	North	19.1105	2270 KVA Skoda	Repair of engine block
790	787	Recron Synthetics Ltd.	Allahabad	North	21.1105	2270 KVA Skoda	Honing and boring of Cylinder Liners
791	788	SRF Ltd.	Bhind, MP	North	22.11.05	2270 KVA Skoda	Honing and boring of Cylinder Liners
792	789	ISGEC	Yamunanagar	North	28.11.05	Shaft	Grinding of eccentric shaft
793	790	Winsome Yarn Ltd.	Patiala	North	29.11.05	2.5 MW Kirloskar Pielstick	Repair of Cylinder Liners
794	791	Indraprastha Gas Ltd.	New Delhi	North	30.11.05	Waukesha	Piston Rod
795	792	Indian Oil Corporation Ltd.	Chaksu	North	01.12.05	Allen	Rapair of crankshaft
796	793	Recron Synthetics Ltd.	Allahabad	North	03.12.05	2270 KVA Skoda	Rapair of crankshaft
797	794	Northern Railway	Shakurbasti	North	05.12.05		Engine block
798	795	Orient Express Ship Management Ltd	Mumbai	West	08.12.05	Daihatsu	Insitu grinding of Crankshaft
799	796	Trident Engineering	Chennai	South	12.12.05	730 KVA SKL	Rapair of crankshaft
800	797	Chidambaram Shipcare Pvt. Ltd.	Chennai	South	12.12.05	Hitachi B&W	Insitu grinding of Crankshaft
801	798	Walchandnagar	Pune	West	13.12.05	1000 KVA Rumo	Rapair of crankshaft
802	799	KL Steel Ltd	Ghaziabad	North	13.12.05	1200 HP MAN	Repair of engine block
803	800	Fleet Management India Pvt Ltd	Mumbai	West	14.12.05	Werkspoor Engine	Inspection of crankshaft
804	801	Ganga International	New Delhi	North	21.12.05	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
805	802	National Fertiliser Ltd	Naya Nangal	North	22.12.05	Spares	Slide gate for material handling valve
806	803	Kirloskar Oil Engines Ltd.	Nashik	West	23.12.05	2.5MW Pielstic	Honing and boring of Cylinder Liners
807	804	Sea Lion ship Management Pvt Ltd	Mumbai	West	26.12.05		Insitu grinding of Crankshaft, Straightening of crankshaft
808	805	Indian Rayon Ind. Ltd.	Veraval, Guj	West	30.12.05	2270 KVA Skoda	Repair of C.R. Housings
809	806	Indian Rayon Ind. Ltd.	Veraval, Guj	West	30.12.05	2270 KVA Skoda	Repair of lower crankcase
810	807	National Fertiliser Ltd	Naya Nangal	North	09.01.06	Spares	Slide gate for material segregating valve
811	808	Ganga International	New Delhi	North	09.01.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
812	809	Ganga International	New Delhi	North	09.01.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
813	810	ACE Glass Container	Rishikesh	North	14.01.06	860 KVA Skoda	Grinding & White Metalising of Crankshaft
814	811	Jindal Pipes Ltd	Ghaziabad	North	17.01.06	1000 KVA Russian	Inspection of crankshaft
815	812	Neel Metal Product Ltd	Gurgaon	North	17.01.06	1376 BHP Mirrlees	insitu Grinding of crankshaft
816	813	Five Star Shipping Co	Mumbai	West	20.01.06	Daihatsu	insitu Grinding of crankshaft
817	814	Modern Petrofils	Baroda	West	03.02.06	2270 KVA Skoda	Rapair of crankshaft
818	815	Modern Petrofils	Baroda	West	03.02.06	2270 KVA Skoda	Repairing of Engine Block
819	816	Modern Petrofils	Baroda	West	03.02.06	2270 KVA Skoda	Metal stitching of MJ Housing
820	817	GIS Industries	Sangrur, PJB	North	03.02.06	860 KVA Skoda	Grinding of Crankshaft

	A	B	C	D	E	F	G
821	818	GIS Industries	Sangrur, PJB	North	03.02.06	860 KVA Skoda	Machining of Bearings
822	819	Ganga International	Delhi	North	06.02.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
823	820	Kirloskar Oil Engines Ltd.	Nashik	West	14.02.06	2.5 MW Kirloskar Pielstick	Boring & Honing of Cylinder Liner
824	821	IOCL, Rajkot	Rajkot	West	17.02.06	S37G Allen Engine	Repair of Connecing Rods
825	822	Rico Auto industries	Khandsa, Gurgaon	North	20.02.06	2270 KVA Skoda	Repair of Connecing Rods
826	823	Indraprastha Gas Ltd.	Delhi	North	27.02.06	Caterpillar	Repair of Connecing Rods, inspection of camshaft
827	824	Indraprastha Gas Ltd.	Delhi	North	27.02.06	Compressor	Repair of piston rods
828	825	SPL Ltd	Bahadurgarh	North	28.02.06	1500 KVA Caterpillar	Inspection of engine block
829	826	Ganga International	Delhi	North	02.03.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
830	827	Ganga International	Delhi	North	02.03.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
831	828	KL Concast Pvt Ltd	Ghaziabad	North	03.03.06	1000 KVA Mirrlees	Grinding of Crankshaft
832	829	KL Concast Pvt Ltd	Ghaziabad	North	03.03.06	1100 Kva SKL DG Set	Grinding of Crankshaft
833	830	SRF Ltd.	Bhind, MP	North	03.03.06	2270 KVA Skoda	Repair of crankshft, LCC & Cylinder Liners
834	831	EM-G-EM Engg	Belapur, Mumbai	West	06.03.06	12PC 2V Pielstic	Onsite polishing of crankshaft
835	832	Neel Metal Product Ltd	Faridabad	North	07.03.06	1376 BHP Mirrlees	Insitu grinding of crankshaft by 1 mm
836	833	Gujrat Gas Co Ltd	Ankleswar	West	09.03.06	Mora Compressor	Rebuilding of crankshaft
837	834	Rajashree Polyfils Ltd	Bharuch	West	11.03.06	2270 KVA Skoda	On site repair of Axial Bearing Seating Area
838	835	Recron Synthetics Ltd.	Allahabad	North	11.03.06	2270 KVA Skoda	Repair of LCCt & Supply of undersize bearing
839	836	Ganga International	Delhi	North	18.03.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
840	837	ISGEC	Yamunanagar	North	21.03.06	Shaft	Grinding of eccentric shaft
841	838	Indraprastha Gas Ltd.	Delhi	North	27.03.06	Waukesha	Repair of Crankshaft, Engine Block, C.R Housings, cam shaft
842	839	ISGEC	Yamunanagar	North	28.03.06	Shaft	Grinding of eccentric shaft
843	840	ISGEC	Yamunanagar	North	04.04.06	Shaft	Grinding of Drive shaft
844	841	ISGEC	Yamunanagar	North	10.04.06	Liners	Honing of Cylinder Liners
845	842	DCW	Patiala	North	11.04.06	Crankshaft of WDS4	Reclamation of Crankshaft
846	843	Indian Rayon	Veraval, Guj	West	11.04.06	2270 KVA Skoda	Repair of C.R. Housings
847	844	ISGEC	Yamunanagar	North	19.04.06	Liners	Honing of Cylinder Liners
848	845	Chidambaram Shipcare Pvt. Ltd.	Chennai	South	20.04.06	B&W	Insitu grinding of 1 No. C.R. Pin
849	846	Royal Ceramics	Nigeria	Overseas	05.05.06	860 KVA Skoda	Insitu grinding of Crankshaft
850	847	Indraprastha Gas Ltd.	New Delhi	North	08.05.06	Caterpillar	Repair of Crankshaft, LCC, C.R Housing, Camshaft
851	848	Ganga International	New Delhi	North	12.05.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
852	849	Kirloskar Oil Engines Ltd.	Pune	West	16.05.06	2.5MW Kirloskar Pielstick	Boring & Honing of Cylinder Liner
853	850	Chidambaram Shipcare Pvt. Ltd.	Chennai	South	31.05.06	B&W	Insitu grinding of 1 No. C.R. Pin
854	851	Ganga International	New Delhi	North	03.06.06	T-72 Tank	Line biring of engine blockof V-46 , T 72 tank
855	852	Garden Silk Mills Ltd.	Surat	West	08.06.06	5.5MW sulzer	Repair of Crankshaft
856	853	Rashtriya Chemicals & Fertilizers Ltd.	Raigad	West	09.06.06	Gear Box	Metal Stitching of Gear Box Casing
857	854	Aditya Birla Nuvo Ltd.	Veraval, Guj	West	10.06.06	2270 KVA Skoda	Repair of C.R. Housings
858	855	Recron Synthetics Ltd.	Allahabad	North	15.06.06	2270 KVA Skoda	Repair of LCC & Liners
859	856	Envoy Oil Industries	Nigeria	Overseas	03.07.06	Crane	Supply of Crane
860	857	Ganga International	New Delhi	North	04.07.06	T-72 Tank	Line Boring of Engine Block
861	858	Raj Steel Rolling Mills	Mandi Gobindgarh	North	08.07.06	2400HP Mirrlees Blackstone	Repair of Crankshaft and LCC
862	859	V. S. Dempo & Co. Pvt. Ltd.	Goa	South	10.07.06	Daihatsu	Repair of C.R Housings

	A	B	C	D	E	F	G
863	860	Lucky Marine Service	Kutch	West	13.07.06	Daihatsu	Insitu grinding of Crankshaft
864	861	Indian Oil Corpn. Ltd.	Chaksu	North	14.07.06	Allen	Insitu alignment by Easy Laser System
865	862	Indian Oil Corpn. Ltd.	Chaksu	North	17.07.06	Allen	Repair of Con. Rods
866	863	Indraprastha Gas Ltd.	New Delhi	North	18.07.06	Caterpillar	Repair of Crankshaft, LCC & C.R Housings
867	864	Indraprastha Gas Ltd.	New Delhi	North	18.07.06	Piston Rod	Repair of piston rods
868	865	Empire Jute Co. Ltd.	West Bengal	East	27.07.06	1100 KVA SKL	Repair of Crankshaft
869	866	V. S. Dempo & Co. Pvt. Ltd.	Goa	South	28.07.06	Daihatsu	Repair of Con. Rods
870	867	Jaypee Rewa Cement	Rewa	North	01.08.06	6 MW Man B & W	Repair of Crankshaft
871	868	KRBL Limited	Gautam Budh Nagar	North	04.08.06	1000 KVA Caterpillar	Repair of Crankshaft
872	869	Vikram Ispat Ltd	Raigad	West	19.08.06	3250 KVA Skoda	Repair of CR Housings
873	870	Ganga International	New Delhi	North	21.08.06	T-72 Tank	Line Boring of Engine Block
874	871	Indian Oil Corpn. Ltd.	Rajkot	West	23.08.06	Allen	Repair of Cylinder Heads
875	872	Recron Synthetics Ltd.	Allahabad	North	25.08.06	2270 KVA Skoda	Repair of LCC
876	873	Triveni Textile Ind.P. Ltd.	Nepal	Overseas	01.09.06	405 KVA Skoda	Grinding of crankshaft, machining of bearing, line boring and remetalting of bearing
877	874	Kirloskar Oil Engines Ltd.	Nashik	West	06.09.06	2.5 MW Kirloskar Pielstick	Boring & Honing of Cylinder Liner
878	875	Lucky Marine Service	Kutch	West	07.09.06	Daihatsu 6PSHT-26D D.G. Set	Insitu grinding of Crankshaft
879	876	M. Harakhji & Sons	Bhavnagar	West	09.09.06	Different DG sets	Polishing of 7 Nos. Crankshafts
880	877	Recron Synthetics	Allahabad	North	13.09.06	2270 KVA Skoda	Repair of Lower Crankcase
881	878	Gemi Motors India Pvt. Ltd.	Faridabad	North	15.09.06	1000 KVA Caterpillar	Repair of crankshaft
882	879	Indraprastha Gas Ltd.	New Delhi	North	16.09.06	Caterpillar	Repair of Crankshaft, LCC, Con. Rod Housings
883	880	Indraprastha Gas Ltd.	New Delhi	North	16.09.06	Waukesha	Repair of Crankshaft, LCC, Con. Rod Housings
884	881	Shreyans Industries Ltd.	Sangrur, PJB	North	21.09.06	950 KVA Sulzer	Insitu grinding of C.R Pin
885	882	Winsome Yarn Ltd.	Patiala	North	07.10.06	Rotor shaft	Repair of Rotor shaft
886	883	Elegant Dyeing & Processing Ltd.	Gurgaon	North	08.10.06	800 KVA Wartsila	Repair of Crankshaft, LCC
887	884	Kutch Chemicals Ind. Ltd.	Kutch	West	11.10.06	2.5 MW Kirloskar Pielstick	Boring & Honing of Cylinder Liner
888	885	Rajashree Polyfils Ltd	Bharuch	West	11.10.06	2270 KVA Skoda	Repair of Crankshaft, LCC & Connecting Rod
889	886	Sterling Biotech Ltd.	Vadodara	West	13.10.06	2270 KVA Skoda	Repair of LCC & C.R Housings
890	887	Gujarat Ambuja Cement	Gujarat	West	11.11.06	2.5MW Kirloskar Pielstick	Boring & Honing of Cylinder Liner
891	888	Indraprastha Gas Ltd.	New Delhi	North	16.11.06	Waukesha Engine	Repair of Engine Block & Connecting Rod
892	889	Kirloskar Oil Engines Ltd.	Nashik	West	21.11.06	2.5.MW Kirloskar Pielstick	Insitu grinding of C.R Pin
893	890	ITC Ltd	Khammam	South	22.11.06	2270KVA CKD	Insitu grinding of C.R Pin
894	891	DCW	Patiala	North	11.12.06	Crankshaft of WDS4	Crankshaft Grinding & Rebuilding
895	892	Maihar Cement Ltd	Satna	North	11.12.06	Fuji 4MW	Repair of Crankshaft
896	893	Lachman Das & Sons	New Delhi	North	12.12.06	Sulzer	Repair of Crankshaft
897	894	Steamships Shipping	Mumbai	West	13.12.06	MV Ispat	Repair of Crankshaft
898	895	Birla Tyres	Orissa	East	15.12.06	2270 KVA Skoda	Repair of Crankshaft ,Line boring of LCC & Rebuilding of M/J
899	896	Eastern Textile Inds.Ltd	Nepal,	Overseas	22.12.06	405 KVA Skoda	Insitu Grinding of crankpin
900	897	Indian Oil Corpn Ltd	Chaksu	North	04.01.07	Allen	Repair of Crankshaft
901	898	ITC Ltd	Khammam	South	17.1.07	2270KVA CKD	Insitu Grinding cranpin & Repair of Con Rods Housing
902	899	Indian Oil Corpn.Ltd	Chaksu	North	5.2.07	Allen	Repair of Crankshaft
903	900	MM Steel & Power Pvt Ltd	Tamil nadu	South	21.2.07	3.5.MW Deutz	Insitu Grinding of crankpin
904	901	Swastik Power Adis	New Delhi	North	24.2.07	860.KVA CKD	Repair of crankshaft

	A	B	C	D	E	F	G
905	902	Moser Bear India Ltd	Noida	North	26.2.07	6 MW Wartsila	Machining of cylinder liner
906	903	Elegant Dyeing & Processing Ltd.	Gurgaon	North	3.3.07	780.KVA Wartsila	Repair of crankshaft
907	904	Vidya Rolling Mills	Shahjahanpur	North	7.3.07	450 KVA Wartsila	Repair of crankshaft
908	905	Applicomp India Ltd	Bangalore	South	5.3.07	2.5.MW Kirloskar Pielstick	Repair of crankshaft
909	906	MSC Ship Management Hongkong Ltd	Hong Kong	Overseas	8.3.07	2.5.MW Deutz	Insitu Grinding of crankpin
910	907	Rajasthan Spinning MillsLtd.	Ringas	North	9.3.07	2.5.MW Kirloskar Pielstick	Repair of Cylinder Liners
911	908	Sterling Biotech Ltd.	Vadodara	West	12.3.07	2270 KVA CKD	Repairing C.R.Housing
912	909	Neel Metal Product Ltd	Gurgaon	North	19.3.07	Mirlees Blackstone	Repair of crankshaft
913	910	Consolidated Coin Co.	Faridabad	North	19.3.07	824TS Wartsila	Repair of crankshaft
914	911	NFL Guna	Guna, M.P.	North	24.3.07	Ammonia Feed Pump	Repair of crankshaft
915	912	Winsome Yarn Ltd.	Patiala, Pb.	North	07.04.2007	Cylinder Liners	Repair of Cylinder Liners
916	913	Neel Metal Product Ltd	Gurgaon	North	13.04.2007	Mirlees Blackstone	Repair of Turbo Charger
917	914	Indian Petrochemicals Corporation Ltd.	Allahabad, UP	North	16.04.2007	CKD - 2270 KVA	Repair of Lower Crank Case
918	915	Neel Metal Product Ltd	Gurgaon	North	16.04.2007	Mirlees Blackstone	Repairing C.R.Housing
919	916	Field Gun Factory	Kanpur, UP	North	25.04.2007	High pressure Pump of Press	Repair of crankshaft
920	917	ABG Shipyard	Mumbai	West	25.04.2007	Ship	Repair of crankshaft
921	918	Indraprastha Gas Ltd.	New Delhi	North	27.04.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
922	919	Indian Petrochemicals Corporation Ltd.	Allahabad, UP	North	16.04.2007	CKD-2270 KVA, D.G.-1	Repair of Lower Crank Case
923	920	Indraprastha Gas Ltd.	New Delhi	North	30.04.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
924	921	Ganga International	New Delhi	North	30.04.2007	V-46-6,T-72 Tank	Repair of Engine Block
925	922	Agri Chemicals Ltd., A/c Royal Ceramics Ltd.	Suleja - Nigeria	Overseas	09.05.2007	Skoda - 860 KVA	Repair of Crank Shaft
926	923	Indraprastha Gas Ltd.	New Delhi	North	29.05.2007	Caterpillar	Repair of Crankshaft, Cam Shaft, & Engine Block
927	924	Indraprastha Gas Ltd.	New Delhi	North	04.06.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
928	925	Indraprastha Gas Ltd.	New Delhi	North	08.06.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
929	926	Agri Chemicals Ltd., A/c Royal Ceramics Ltd.	Suleja - Nigeria	Overseas	11.06.2007	Skoda - 860 KVA	Repair of CrankShaft
930	927	Orient Ceramics & Indus Ltd.	Sikandrabad - UP	North	15.06.2007	Waukesha- 2.2 MW	Repair of CrankShaft
931	928	The Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	18.06.2007	Item Code : L-CMO1226531	Repair of Cylinder Liners
932	929	Winsome Yarn Ltd.	Patiala - Pb.	North	20.06.2007	Kirloskar Pielstick-2.5MW	Repair of Cylinder Liners
933	930	Indraprastha Gas Ltd.	New Delhi	North	20.06.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
934	931	Northern Railway	Amritsar - Pb.	North	26.06.2007	Diesel Loco	Repair of CrankShaft
935	932	Ganga International	New Delhi	North	30.06.2007	V-46-6,T-72 Tank	Repair of Engine Block
936	933	Indraprastha Gas Ltd.	New Delhi	North	05.07.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
937	934	Indian Petrochemicals Corporation Ltd.	Allahabad, UP	North	17.07.2007	CKD-2270 KVA,	Repair of Lower Crank Case
938	935	Indraprastha Gas Ltd.	New Delhi	North	26.07.2007	Compressor	Repair of piston rods
939	936	Northern Railway	Shakurbasti - Delhi	North	26.07.2007	Diesel Loco	Crankshaft Straightening & Polishing, Line boring of Engine Block
940	937	Ganga International	New Delhi	North	28.07.2007	V-46-6,T-72 Tank	Line Boring of Engine Block
941	938	Winsome Yarn Ltd.	Patiala - Pb.	North	01.08.2007	Cummins - 1250 KVA	Repair of Crank Shaft & Crank Case
942	939	K.L. Concast Limited	Ghaziabad	North	01.08.2007	SKL - 1100 KVA	Grinding of Crank shaft
943	940	Kirloskar Oil Engines Ltd.	Ambd. - Nashik	West	07.08.2007	Kirloskar Pielstick-2.5MW	Cylinder Liners Repairing
944	941	Indraprastha Gas Ltd.	New Delhi	North	16.08.2007	Compressor	Repair of piston rods
945	942	Ganga International	New Delhi	North	18.07.2007	V-46-6,T-72 Tank	Line Boring of Engine Block
946	943	M. Harakhji & Sons	Bhavnagar	West	21.08.2007	Pielstick 16PC 2V	Polishing of 8 Nos. Crankshafts

	A	B	C	D	E	F	G
947	944	Indraprastha Gas Ltd.	New Delhi	North	25.08.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
948	945	Indraprastha Gas Ltd.	New Delhi	North	31.08.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
949	946	Indraprastha Gas Ltd.	New Delhi	North	05.09.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
950	947	Ganga International	New Delhi	North	06.09.2007	V-46-6,T-72 Tank	Line Boring of Engine Block
951	948	Rai & Sons	New Delhi	North	13.09.2007	Skoda - 2270 KVA	Boring & Honing of Cylinder Liners
952	949	Andhra Petrochemicals Ltd.	Visakhapatna - Andhra Pradesh	South	18.09.2007	CKD - 2270 KVA	Crank shaft- Grinding, Polishing & Straightening and Engine Block - Line Boring & Alignment
953	950	Ganga International	New Delhi	North	19.09.2007	V-46-6,T-72 Tank	Line Boring of Engine Block
954	951	Prime Hydraulics & Pneumatics Pvt. Ltd.	Gurgaon	North	25.09.2007	Hydraulic Cylinder Housing	Honing of Hydraulic Cylinder Housing
955	952	Indraprastha Gas Ltd.	New Delhi	North	29.09.2007	Compressor	Rebuilding and Grinding of Compressor Shaft
956	953	Indraprastha Gas Ltd.	New Delhi	North	29.09.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
957	954	AMCO India Ltd.	Alwar - Rajasthan	North	03.10.2007	Nohab Pollar - 1250 KVA	Crank shaft- Grinding, Polishing
958	955	Third Wave Services Pvt. Ltd.	New Delhi	North	09.10.2007	Cummins	Crank shaft- Grinding, Polishing & Straightening and Engine Block - Line Boring
959	956	Reliance Industries Ltd.	Allahabad - UP	North	13.10.2007	CKD - 2270 KVA	Repairing of lower crank case
960	957	Ramalingam Mills Ltd.	Aruppukattal	South	17.10.2007	CKD - 860 KVA	Crank shaft- Grinding, Polishing & Straightening and Engine Block - Line Boring
961	958	Wartsila India Ltd.	Noida	North	18.10.2007	Wartsila - 1.5 MW	Connecting Rods - Straightening, Parallelism and Center Distance
962	959	Indraprastha Gas Ltd.	New Delhi	North	19.10.2007	Caterpillar	Repair of Crankshaft, Cam Shaft, & Engine Block
963	960	Reliance Industries Ltd.	Allahabad - UP	North	20.10.2007	CKD - 2270 KVA	Metal stitching on cracks in lower crank case
964	961	Indraprastha Gas Ltd.	New Delhi	North	25.10.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
965	962	Cadila Health Care Ltd.	Ahmedabad	West	08.11.2007	Kirloskar Pielstick-2.5MW	Honing of Cylinder Liners
966	963	Ganga International	New Delhi	North	14.11.2007	V-46-6,T-72 Tank	Line Boring of Engine Block
967	964	AMCO India Ltd.	Alwar - Rajasthan	North	16.11.2007	Nohab Pollar - 1250 KVA	Rectification and Hydraulic testing of Ctlinder Heads
968	965	Indraprastha Gas Ltd.	New Delhi	North	19.11.2007	Waukesha	Repair of Crankshaft, Cam Shaft, Engine Block & Connecting Rods
969	966	Leo Shipping Co. Ltd.	Belapur, Mumbai	West	23.11.2007	Deutz	Straightening of crankshaft by pinning process & Line Boring of Engine Block
970	967	Elegant Dyeing & Processing Ltd.	Gurgaon	North	26.11.2007	Drive Shaft	Removal of existing old damaged stem of drive shaft
971	968	Andhra Petrochemicals Ltd.	Andhra Pradesh	South	30.11.2007	CKD - 2270 KVA	Repair of Connecting Rod with Housings
972	969	Northern Railway	New Delhi	North	30.11.2007	Engine Block of Loco	Reclamation of Engine Block
973	970	Reliance Industries Ltd.	Allahabad	North	3.12.2007	CKD - 2270 KVA	In situ grinding of CR Pin No.5
974	971	Leo Shipping Co. Ltd.	Mumbai	West	04.12.2007	Deutz D.G. Set	In situ grinding of 1 No. Main Journal
975	972	Reliance Industries Ltd.	Allahabad	North	05.12.2007	CKD - 2270 KVA	Rebuilding of Main Journal No.1
976	973	Reliance Industries Ltd.	Allahabad	North	05.12.2007	CKD - 2270 KVA	Grinding of C/S
977	974	Reliance Industries Ltd.	Allahabad	North	05.12.2007	CKD - 2270 KVA	Repair of Lower Crank Case
978	975	Indraprastha Gas Ltd.	New Delhi	North	14.12.2007	Waukesha Engine	Repair of Engine Block
979	976	Ganga International	New Delhi	North	19.12.2007	V-46 T-72 Tank	Repair of Engine Block
980	977	Indian Oil Corpn.	Rajkot	West	19.12.2007	Allen Engine	Repair of Cylinder Head
981	978	Industrial & Agro Tractor Parts	Indore	North	22.12.2007	Cummins Engine	Inspection of Cummins Engine
982	979	Modern Petrofils	Vadodara	West	21.12.2007	CKD - 2270 KVA	Grinding of C/S & Line boring of Engine Block
983	980	Lakshmi Precision Screws Ltd./	Rohtak	North	05.01.2008	Press Crankshaft	Grinding of C/S
984	981	Rajashree Polyfils Ltd	Baruch	West	07.01.2008	CKD - 2270 KVA	Metal stitching of LCC
985	982	Bimal Services Ltd.	Vadodara	West	14.01.2008	Yanmar 1250 KVA	Grinding of 1 No. CR Pin
986	983	Techonomy System - A B	Sweedden	Overseas	28.01.2008	Pielstick 12 PC 2V	Grinding of Crank Shaft
987	984	Royal Ceramics Ltd.	Lagos - Nigeria	Overseas	29.01.2008	Skoda - 860 KVA	Spares for Engine Block
988	985	Indraprastha Gas Ltd.	New Delhi	North	02.02.2008	Waukesha	Repair of Engine

	A	B	C	D	E	F	G
989	986	Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	04.02.2008	Hydraulic Press	Repair of Eccentric Shaft - (L.H.)
990	987	Hi-Tech Gears Ltd.	Bhiwadi - Rajasthan	North	04.02.2008	Forging Press	Grinding of Crank Shaft
991	988	Modi Rubber Limited	Meerut - U.P.	North	04.02.2008	CKD - 860 KVA	Grinding of Crank Shaft & Remetalling & Machining Job
992	989	EM-G-EM Engg. & Cons.	Belapur, Mumbai	West	06.02.2008	Fuji - 12 V 32 X	Repairing & Grinding of Crank Shaft
993	990	Reliance Industries Ltd.	Allahabad - UP	North	08.02.2008	CKD - 2270 KVA	Repairing of Lower Crank Case
994	991	Northern Railway Shakurbasti	Delhi	North	08.02.2008	Loco No. 19608	Crank Shaft Grinding and Line Boring of Engine Block
995	992	Indraprastha Gas Ltd.	New Delhi	North	13.02.2008	Waukesha	Repair of Engine, Crank Shaft, Con. Rods & Cam Shaft
996	993	Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	14.02.2008	Hydraulic Press	Repair of Eccentric Shaft - (R.H.)
997	994	KSS Shipping Services	Mumbai	West	03.03.2008	Daihatsu- 6 DSD-22	In-situ Grinding of Crank Shaft in Vessel
998	995	M. Harakhji & Sons / A/c B.V. Indumij Motoren	Bhavnagar-Gujarat / Netherland	Overseas	12.03.2008	Pielstick - 10 PC 2.5 V	Grinding of Crank Shaft
999	996	EM-G-EM Engg. & Cons.	Belapur, Mumbai	West	14.03.2008	Fuji - 4 MW, 12 V 32	Repairing & Grinding of Crank Shaft
1000	997	Indian Oil Corporation Ltd.	Rajkot - Gujarat	West	15.03.2008	Allen - 8 S 7 G	Reconditioning of connecting rods
1001	998	Indraprastha Gas Ltd.	New Delhi	North	17.03.2008	Caterpillar	Repair of Crankshaft, Cam Shaft, & Engine Block
1002	999	Third Wave Services Pvt. Ltd.	New Delhi	North	19.03.2008	Cummins - KTA 2300	Grinding of Crank Shaft
1003	1000	Reliance Industries Ltd.	Allahabad - UP	North	25.03.2008	DG Set - 12, 15 & 16	Honing of Cylinder Liners
1004	1001	Ganga International	New Delhi	North	27.03.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings
1005	1002	Indraprastha Gas Ltd.	New Delhi	North	31.03.2008	Waukesha	Repair of Crank Shaft, Con. Rods & Cam Shaft
1006	1003	Reliance Industries	Allahabad - UP	North	12.04.2008	CKD - 2270 KVA	Grinding of Crank Shaft
1007	1004	Andhra Petro Chemicals Ltd.	Andhra Pradesh	South	12.04.2008	CKD - 2270 KVA	Rectification of Connecting Rods
1008	1005	Indraprastha Gas Ltd.	New Delhi	North	15.04.2008	Caterpillar	Repair of Cater Pillar Engine Block
1009	1006	Modern Petrofills	Bamangaon - Baroda	West	15.04.2008	CKD - 2270 KVA	Rebuilding of M.J. Housing & Repairing of Connecting Rods
1010	1007	Lakshmi Precision Screws Ltd/.	Rohtak	North	21.04.2008	Forging Press	Grinding of Crank Shaft
1011	1008	SNP Shipping Services Pvt. Ltd.	Colaba - Mumbai	West	23.04.2008	Daihatsu	On-site Grinding of Crankshaft in Vessel MV AS SALAAM at Dhoula / Camreoun West Africa
1012	1009	Kirloskar Oil Engines Ltd.	Ahmedabad - Nasik	West	23.04.2008	Kirloskar Pielstick-P PA 6 L 280	On-site Polishing of Crank Shaft
1013	1010	Indraprastha Gas Ltd.	New Delhi	North	24.04.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1014	1011	Indraprastha Gas Ltd.	New Delhi	North	28.04.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1015	1012	Reliance Industries	Allahabad - UP	North	01.05.2008	CKD - 2270 KVA	Honing of Cylinder Liners
1016	1013	Reliance Industries	Allahabad - UP	North	03.05.2008	CKD - 2270 KVA	Repair of Lower Crank Case
1017	1014	Aditya Birla Nuvo Ltd.	Junagarh - Gujarat	West	08.05.2008	CKD - 2270 KVA	Grinding of Crank Shaft
1018	1015	Aditya Birla Nuvo Ltd.	Junagarh - Gujarat	West	08.05.2008	CKD - 2270 KVA	Rebuilding & Line boring of Lower Crank Case
1019	1016	Shivani Locks Pvt. Ltd.	Faridabad	North	09.05.2008	Cummins - 750 KVA	Grinding & Straightening of Crankshaft
1020	1017	Ganga International	New Delhi - Cant	North	10.05.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 4 Engine Blocks
1021	1018	Tania Hydraulic Machines	Ludhiana, Pb.	North	13.05.2008	Hydraulic Cylinder Housings	Honing of Hydraulic Cylinder Housings
1022	1019	Kirloskar Oil Engines Ltd. on A/c Nuitech Machine Ltd.-Sharanpur	Ahmdabad - Nasik	West	15.05.2008	Kirloskar Pielstick-2.5 MW	Boring and Honing of Cylinder Liners
1023	1020	Indraprastha Gas Ltd.	New Delhi	North	26.05.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1024	1021	Harakhji & Sons on A/c Indumij Motoren - Netherland	Netherland	Overseas	26.05.2008	Pielstick - 18 PC 2 V	Inspection, Straightening & Grinding of Crank Shaft-
1025	1022	Harakhji & Sons on A/c Indumij Motoren - Netherland	Netherland	Overseas	26.05.2008	Pielstick - 18 PC 2 V	Inspection, Straightening & Grinding of Crank Shaft-2
1026	1023	Rai & Sons	New Delhi	North	30.05.2008	CKD - 2270 KVA	Metal Stitching of Lube Oil Pump Body
1027	1024	Indraprastha Gas Ltd.	New Delhi	North	04.06.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1028	1025	Ganga International	New Delhi - Cant	North	07.06.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 3 Engine Blocks
1029	1026	Dee Hass Beheer B.V.	Netherland	Overseas	09.06.2008	Pielstick - 16 PC 2 V	Inspection, Grinding & Polishing of Crank Shaft
1030	1027	Indraprastha Gas Ltd.	New Delhi	North	11.06.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft

	A	B	C	D	E	F	G
1031	1028	SRF Limited	Bhind - MP	North	13.06.2008	CKD - 2270 KVA	Repair of Crank Shaft
1032	1029	SRF Limited	Bhind - MP	North	13.06.2008	CKD - 2270 KVA	Repair of Engine Block
1033	1030	Techonomy System - A B	Sweeden	Overseas	16.06.2008	Sulzer - 6 AL - 25/30	Repair of Crank Shaft
1034	1031	Techonomy System - A B	Sweeden	Overseas	16.06.2008	Pielstick - 6 PC - 2 L	Repair of Crank Shaft
1035	1032	Indraprastha Gas Ltd.	New Delhi	North	17.06.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1036	1033	Ganga International	New Delhi - Cant	North	19.06.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 4 Engine Blocks
1037	1034	Ganga International	New Delhi - Cant	North	10.07.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 5 Engine Blocks
1038	1035	Lucky Marine Service	Kutch - Gujarat	West	14.07.2008	Yanmar 6 - MAL HTS	In-situ Grinding of Crank Shaft at Gandhidham Port
1039	1036	KSS Shipping Services	Navi Mumbai	West	24.07.2008	Main Engine on Vessel	On-site Metal Stitching of Crank Shaft
1040	1037	Kirloskar Oil Engine Ltd.	Ahmadabad - Nasik	West	29.07.2008	Kirloskar Pielstick - 6 PA 6 L 280	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1041	1038	Ganga International	New Delhi - Cant	North	30.07.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 3 Engine Blocks
1042	1039	National Aluminium Co. Ltd.	Orissa	East	04.08.2008	TBTD - A3 M, KPC	Inspn., Straightening, Remetalling, Grinding and Polishing of Crank Shaft
1043	1040	Indraprastha Gas Ltd.	New Delhi	North	05.08.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1044	1041	Alang MaritimeTrading Housing of Ship Machinery	Bhavnagar - Gujarat	West	07.08.2008	MAK - 6M551 AK	Inspection & Straightening of Crank Shaft - 2 Nos.
1045	1042	Indraprastha Gas Ltd.	New Delhi	North	05.08.2008	Waukesha & Caterpillr	2 Sets Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1046	1043	Wallan Shipmanagement Ltd.	Hongkong	Overseas	10.08.2008	Man- B&W 5L - 28/32	Onsite Grinding & Polishing of crankshaft in Vessel
1047	1044	Satia Paper Mills Ltd.	Muksar - Punjab	North	28.08.2008	CIMG Pump	Appx. 10" long appx. Metal Stitching of Pump by Imported Key & Lock
1048	1045	Winsome Yarn Ltd.	Patiala - Pb.	North	28.08.2008	Kirloskar Pielstick - 2.5 MW	Rectification in Engine Block
1049	1046	SPL Limited	Bahadurgarh - Haryana	North	29.08.2008	Sulzer - 12 ATV 25D 2.2 MW	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1050	1047	Indraprastha Gas Ltd.	New Delhi	North	29.08.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1051	1048	Jindal Stainless Steel Ltd.	Hissar - Haryana	North	30.08.2008	Wartsila - 18 V-32	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1052	1049	Eco-Friendly Association	New Delhi	North	08.09.2008	Kirloskar - 82.5 KVA	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1053	1050	Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	10.09.2008	Forging Press	Grinding of Eccentric Shaft
1054	1051	Indraprastha Gas Ltd.	New Delhi	North	16.09.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1055	1052	Electro Steel Casting Ltd.	Kolkata - West Banga	East	23.09.2008	CKD - 1450 KVA	Inspection and Metal stitching in L.C.C. and Crank Shaft
1056	1053	Ganga International	New Delhi - Cant	North	30.09.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 8 Engine Blocks
1057	1054	Goodyear India Limited	Ballabgarh-Haryana	North	24.09.2008	Gear & Gear Housing	Line boring of Bull Gear Housing and Grinding of Gear Pin
1058	1055	Indraprastha Gas Ltd.	New Delhi	North	24.09.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1059	1056	Kutch Chemicals Ind. Ltd.	Kutch - Gujarat	West	25.09.2008	Kirlos. Pielstick - 2.5 M	Honing of Cylinder Liners
1060	1057	Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	26.09.2008	Forging Press	Grinding of Eccentric Shaft
1061	1058	Indraprastha Gas Ltd.	New Delhi	North	27.09.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1062	1059	Indumij Marine Logistics B.V.	Netherland	Overseas	29.09.2008	Pielstick - 12 PC 2V	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1063	1060	Gillanders Arbuthnot & Co. Ltd	Sangrur, Punjab	North	08.10.2008	CKD - 860 KVA	Inspn., Straightening, Grinding and Polishing of Crank Shaft
1064	1061	Indian Sugar & General Engg. Corpn.	Yamunanagar-Haryana	North	10.10.2008	Forging Press	Grinding of Eccentric Shaft
1065	1062	Electro Steel Casting Ltd.	Kolkata - West Bangal	East	13.10.2008	CKD - 1450 KVA	Line boring of Main Bearings and Straightening of Crank Shaft
1066	1063	Indraprastha Gas Ltd.	New Delhi	North	20.10.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1067	1064	Mahaan Protiens Limited	Kosi Kalan - Mathura (UP)	North	20.10.2008	MAK - 8 PSHTC - 260 D	Rectification of Engine Block and Connecting Rods and Inspn., Straightening & Grinding of Crank Shaft
1068	1065	Indraprastha Gas Ltd.	New Delhi	North	03.11.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1069	1066	MSC Ship Management Hongkong Ltd	Hong Kong	Overseas	03.11.2008	Vessel MSC LANA	On-site Inspection & Grinding of Alternator Shaft
1070	1067	Indraprastha Gas Ltd.	New Delhi	North	07.11.2008	Waukesha	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1071	1068	Indraprastha Gas Ltd.	New Delhi	North	07.11.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1072	1069	Indraprastha Gas Ltd.	New Delhi	North	03.11.2008	Areal Cimpresor	Repairing of Crank Shaft, Line Boring of Engine Block and Manufacturing of New

	A	B	C	D	E	F	G
1073	1070	Ganga International	New Delhi - Cant	North	11.11.2008	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 8 Engine Blocks
1074	1071	Indumij Marine Logistics B.V.	Netherland	Overseas	12.11.2008	Pielstick - 14 PC 2.5 V	Inspection, Grinding & Polishing of Crank Shaft No.-1
1075	1072	Indumij Marine Logistics B.V.	Netherland	Overseas	12.11.2008	Pielstick - 14 PC 2.5 V	Inspection, Grinding & Polishing of Crank Shaft No.-2
1076	1073	Indumij Marine Logistics B.V.	Netherland	Overseas	12.11.2008	Pielstick - 14 PC 2.5 V	Inspection, Grinding & Polishing of Crank Shaft No.-3
1077	1074	Indian Oil Corporation Ltd.	Purba Madinipur - West Bangal	East	18.11.2008	Allen	In-situ Honing of Cylinder Liners
1078	1075	Shyam Power Tech On A/c Techonomy System AB	Sweeden	Overseas	08.12.2008	Pielstick - 12 PC 2V	Inspection, Grinding & Polishing of Crank Shaft No.-1
1079	1076	Marine Enterprises A/c Indumij Marine Logistics B.V.	Netherland	Overseas	13.12.2008	Pielstick - 12 PC 2V	Inspection, Straightening, Grinding & Polishing of Crank Shaft No.-2
1080	1077	Shyam Power Tech On A/c Indumij Marine Logistics B.V.	Netherland	Overseas	17.12.2008	Pielstick - 12 PC 2V	Inspection, Grinding & Polishing of Crank Shaft No.-3
1081	1078	Shyam Power Tech On A/c Indumij Marine Logistics B.V.	Netherland	Overseas	17.12.2008	Pielstick - 12 PC 2V	Inspection, Grinding & Polishing of Crank Shaft No.-4
1082	1079	Indraprastha Gas Ltd.	New Delhi	North	23.12.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1083	1080	Indraprastha Gas Ltd.	New Delhi	North	22.12.2008	Intermac Compressor	Crank Shaft inspection, rebuilding and grinding
1084	1081	KSS Shipping Services	Navi Mumbai	West	26.12.2008	Emerald - AE3	Inspection, Grinding & Polishing of Crank Shaft at site
1085	1082	Indraprastha Gas Ltd.	New Delhi	North	31.12.2008	Caterpillar	Repair of Engine Block,Crank Shaft, Con.Rods & Cam Shaft
1086	1083	Indraprastha Gas Ltd.	New Delhi	North	31.12.2008	Intermac Compressor	Crank Shaft inspection, rebuilding and grinding
1087	1084	Castle Ship Pvt. Ltd.	Navi Mumbai	West	02.01.2009	Daihatsu	Inspection, Grinding & Polishing of Crank Shaft at Colombo - Sri Lanka
1088	1085	Green Power International Pvt. Ltd.	New Delhi	North	03.01.2009	Deutz	Polishing of Crank shaft at site - Ankleshwar
1089	1086	Ganga International	New Delhi - Cant	North	03.01.2009	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 5 Engine Blocks
1090	1087	Indian Oil Corporation Ltd.	Purba Madinipur - West Bangal	East	07.01.2009	Allen	Honing of Cylinder Liners
1091	1088	Rolls Royce Energy Systems India P.Ltd.	New Delhi	North	07.01.2009	Allen	In-situ Honing of Cylinder Liners
1092	1089	Lakshmi Precision Screws Ltd.	Rohtak - Haryana	North	10.01.2009	Forging Press	Inspection, Rebuilding, Grinding and Polishing of Crank Shaft
1093	1090	Indumij Marine Logistics B.V.	Netherland	Overseas	14.01.2009	Pielstick - 12 PC 2.5 V	Repair of used Crank Shaft
1094	1091	Kirloskar Oil Engines Ltd.	Ahmdabad - Nasik	West	14.01.2009	Kirloskar Pielstick - 6 PA 6 L 280	Polishing and Inspection of Crank shaft
1095	1092	Green Ocean Ship Management Pvt. Ltd.	Navi Mumbai	West	14.01.2009	SW - Diesel Engine	Inspection, Grinding & Polishing of Crank Shaft
1096	1093	Marine Enterprises A/c Indumij Marine Logistics B.V.	Netherland	Overseas	19.01.2009	Pielstick - 18 PC 2V	Inspection, Grinding & Polishing of Crank Shaft
1097	1094	TMB Shipping Pvt. Ltd.	Kolkata - West Bangal	East	31.01.2009	Main Engine on Vessel VIZAG	Inspection, Grinding & Polishing of Crank Shaft
1098	1095	Indumij Marine Logistics B.V.	Netherland	Overseas	09.02.2009	Pielstick - 14 PC 2 V	Inspection, Grinding & Polishing of Crank Shaft
1099	1096	Seven Islands Shipping Ltd.	Andheri - mumbai	West	10.02.2009	Paradeep on Vessel M.T. Vijaydoot	Inspection, Grinding & Polishing of Crank Shaft
1100	1097	Modern Petrofills Ltd.	Baroda - Gujarat	West	14.02.2009	Skoda - 2270 KVA	Crank Shaft Inspection, Straightening, grinding & Polishing
1101	1098	Elin Electronics Ltd.	Ghaziabad - U.P.	North	17.02.2009	Skoda - 860 KVA	Grinding of Crank Shaft & Line Boring of Main Bearings
1102	1099	Eco-Friendly Association	New Delhi	North	17.02.2009	Kirloskar - 125 KVA	Calibration of Cylinder Block, Crank Shaft, Cam Shaft and Connecting Rods
1103	1100	Somany Ceramics Limited	Bahadurgarh - Haryana	North	21.02.2009	Sulzer - 12 ATV 2.2 MW	Rectification of C.R. Housings
1104	1101	Indraprastha Gas Ltd.	New Delhi	North	25.02.2009	Waukesha	Repair 2 Sets of of Engine Block, Crank Shaft, Con.Rods & Cam Shaft
1105	1102	Indraprastha Gas Ltd.	New Delhi	North	26.02.2009	Waukesha	Repair 2 Sets of of Engine Block, Crank Shaft, Con.Rods & Cam Shaft
1106	1103	Ganga International	New Delhi - Cant	North	05.03.2009	V-46-6,T-72 Tank	Line Boring of M.J. Housings of 10 Engine Blocks
1107	1104	Indian Oil Corporation Ltd.	Purba Madinipur - West Bangal	East	07.03.2009	Allen Diesel	Honing of Cylinder Liners at Site Bhirbhum
1108	1105	Aditya Birla Nuvo Ltd.	Junagarh - Gujarat	West	07.03.2009	CKD - 2270 KVA	Grinding of Crank Shaft
1109	1106	Modern Petrofills	Baroda - Gujarat	West	16.03.2009	Skoda - 2270 KVA	Inspection, Straightening, Grinding & Polishing of Crank Shaft
1110	1107	Indumij Marine Logistics B.V.	Netherland	Overseas	17.03.2009	Pielstick - 10 PC 4.1 V	Inspection, Grinding & Polishing of Crank Shaft
1111	1108	Diesel Loco Modernisation Works	Patiala - Punjab	North	19.03.2009	Diesel Loco - 3100 HP	Inspection, Straightening, Rebuilding, Grinding & Polishing of Crank Shaft
1112	1109	Modern Petrofills	Baroda - Gujarat	West	21.03.2009	Skoda - 2270 KVA	On-site Inspection and Line Boring of Lower Crank Case
1113	1110	Indraprastha Gas Ltd.	New Delhi	North	25.03.2009	Intermac Compressor	Inspection and Repair of Connecting Rods
1114	1111	Efecient Business Services Pvt. Ltd.	Mumbai	West	01.04.2009	SKL - 8 NVD 26 / 20	Crank Shaft Inspection, Grinding & Polishing on Vessel at Mundra Port

	A	B	C	D	E	F	G
1115	1112	Lucky Marine Service	Kutch - Gujarat	West	01.04.2009	Yanmar 6 - MAL HTS	Crank Shaft Inspection, Grinding on Vessel at Gangdhidham Port
1116	1113	SRF Limited	Bhind - MP	North	01.04.2009	Kirloskar Pielstick - 9 PC	On-site Inspection, Straightening, Grinding and Polishing of Crank Shaft
1117	1114	Indraprastha Gas Ltd.	New Delhi	North	04.04.2009	Caterpillar	Inspection & Repair of Engine Block, Crank Shaft, Con.Rods & Cam Shaft
1118	1115	Reliance Industries Ltd.	Allahabad - UP	North	08.04.2009	CKD - 2270 KVA	Inspection and Repair of Lower Crank Case
1119	1116	Gulf Liner Shipping Agencies LLC	DUBAI, U.A.E.	Overseas	10.04.2009	On - Vessel	In-Situ Grinding of Crank Shaft on Vessel at site-Mumbai
1120	1117	Uni Products Ltd.	Noida - U.P.	North	11.04.2009	Skoda - 2270 KVA	Metal Stitching and Line Boring of Lower Crank Case
1121	1118	Uni Products Ltd.	Noida - U.P.	North	13.04.2009	Skoda - 2270 KVA	Main Journal Cap of ckd - 2270 KVA Engine Block
1122	1119	Castle Ship Pvt. Ltd.	Navi Mumbai	West	13.04.2009	Daihatsu	Inspection, Grinding & Polishing of Crank Shaft and remove of all cracks
1123	1120	Indraprastha Gas Ltd.	New Delhi	North	15.04.2009	Caterpillar	Inspection & Repair of Engine Block, Crank Shaft, Con.Rods & Cam Shaft
1124	1121	Indian Oil Corporation Ltd.	Purba Madinipur - West Bangal	East	17.04.2009	Work-Order Item 00010	In-situ Honing of Cylinder Liners
1125	1122	Indraprastha Gas Ltd.	New Delhi	North	18.04.2009	Waukesha	Inspection & Repair of Engine Block, Crank Shaft, Con. Rods & Cam Shaft of 2 Sets
1126	1123	Trans Arabian Tech. Services Co. Ltd.	Saudia Arabia	Overseas	23.04.2009	MAN - 1 EA	Line Boring of Engine Block
1127	1124	Trans Arabian Tech. Services Co. Ltd.	Saudia Arabia	Overseas	23.04.2009	MAN - 1 EA	Crank Shaft Inspn., Straightening
1128	1125	Kanco Enterprises Ltd.	Ahmedabad	West	23.04.2009	Kirloskar Oil Engine	Honing of Cylinder Liners
1129	1126	Uni Products Ltd.	Noida - U.P.	North	30.04.2009	CKD - 2270 KVA	Honing of Culinder Liners
1130	1127	Indumij Marine Logistics B.V.	Netherland	Overseas	02.05.2009	Pielstick - 18 PC 2 V	Inspection, Grinding & Polishing of Crank Shaft
1131	1128	Indraprastha Gas Ltd.	New Delhi	North	02.05.2009	Caterpillar Model - G 3408	Inspection & Repair of Engine Block, Crank Shaft, Con.Rods & Cam Shaft
1132	1129	Aditya Birla Nuvo Ltd.	Junagarh - Gujarat	West	06.05.2009	Skoda - 2270 KVA	Inspection & Repair of Engine Block, and Crank Shaft Inspection, Rebuilding, Grinding & Polishing
1133	1130	Indumij Marine Logistics B.V.	Netherland	Overseas	30.05.2009	Pielstick - 12 PC 2 V	Inspection, Straightening, Grinding & Polishing of Crank Shaft - 2 Nos.
1134	1131	Indumij Marine Logistics B.V.	Netherland	Overseas	30.05.2009	Pielstick - 12 PC 2 V	Inspection, Straightening, Grinding & Polishing of Crank Shaft
1135							
1136							
1137							
1138							
1139							
1140							
1141							
1142							
1143							